

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33926

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0326/2020/NS
Date : 25-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Koh Chee Hwee, Jeffrey
Address : Blk 333 Sembawang Close
#05-429
Singapore 750333
Telephone : HP +65 94385476
Type of Claim : Own Damage Claims
Policy No. : 1800145592-01
Vehicle No : **SMG 1822 Y**
Model Code : Audi A3 Sedan 1.4 TFSI CO
Model / Year : Dec-18
Engine No : CZE 846849
Chassis No : WAUZZZ8V3K1008346
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Mar-20
Place of Accident : 335A Sembawang Close Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 1822 Y

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00 /	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	500	\$ 2,450.00	1250
3	To respray front bumper and lhs front fender.	550	\$ 2,000.00	1100
4	To carry out pre-diagnostic check and post-diagnostic check.	S/N	\$ 384.00 /	
TOTAL LABOUR CHARGES		:	<u>\$ 5,194.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 1822 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER ✓ DD	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS ?	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION - LH ?	\$ 36.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	\$ 505.00	
5	FRONT BUMPER CLOSING ELEMENT - LH ?	\$ 280.00	
6	FRONT BUMPER COVER TRIM - LH X	\$ 153.00	
7	WHEEL HOUSING LINER ADAPTER - LH X	\$ 36.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH X	\$ 177.00	
9	FRONT BUMPER SIDE REINFORCEMENT BEAM X	\$ 681.00	
10	FRONT BUMPER FOAM FILLER PIECE X	\$ 178.00	
11	FRONT FENDER - LH ✓ DD	\$ 802.00	
12	FRONT FENDER ATTACHMENT PARTS ?	\$ 68.00	
13	FRONT FENDER BRACE X	\$ 90.00	
14	WHEEL HOUSING LINER SEAL - LH X	\$ 32.00	
15	WHEEL HOUSING LINER - LH X	\$ 159.00	
16	WHEEL HOUSING LINER ATTACHMENT PARTS X	\$ 84.00	
17	LED HEADLIGHT - LH ✓ DR	\$ 5,193.00	
18	MAIN LIGHT ELECTRONICS POWER MODULE - LH ?	\$ 714.00	
19	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$ 524.00	
20	LED WITH HEAT SINK - LH ?	\$ 689.00	
21	HEADLIGHT HOSE - LH X	\$ 38.00	
22	LIGHT CYLINDER - LH X	\$ 134.00	
23	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 12,943.00	
TOTAL LABOUR CHARGES		: \$ 5,194.00	
GRAND TOTAL		: \$ 18,137.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

26/3/72, 7.19pm
Name : Steve (LKK) OD - Not ActL (rm)
Surveyed Date : Excess - ?
Authorised Date : P/P
Excess Cost : Ry Bel sy
Liability : 5 dys
Remarks :

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant