

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33829

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0333/2020/NS
Date : 26-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SLZ 225 C

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Tew Tze Hong (Zhang Shihong)
Address : 65 West Coast Way
#07-26
Singapore 127022
Telephone : HP +65 94376657
Type of Claim : Third Party Claim
Policy No. : 1700033075-02
Vehicle No : **SLR 1214 G**
Model Code : A3 Sedan 1.0 TFSI 8V
Model / Year : Jul-17
Engine No : CHZ 384827
Chassis No : WAUZZZ8V0H1080193
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Mar-20
Place of Accident : 61A Tanah Merah Coast Rd S(498738) Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 1214 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 700	1050.00
3	To respray front bumper and rhs front fender.	\$ 2,000.00 1400	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>5,002.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 1214 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Regis</i>	\$ 1,894.00	+
2	FRONT BUMPER FIXING PARTS	\$ 176.00	+
3	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	+
4	FRONT BUMPER CLOSING ELEMENT - RH	\$ 280.00	+
5	FRONT BUMPER COVER TRIM - RH	\$ 153.00	+
6	WHEEL HOUSING LINER ADAPTER - RH	\$ 36.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 177.00	+
8	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 681.00	+
9	FRONT BUMPER FOAM FILLER PIECE	\$ 178.00	+
10	FRONT FENDER - RH <i>Regis</i>	\$ 802.00	+
11	FRONT FENDER BRACKET - RH	\$ 36.00	+
12	FRONT FENDER BRACE	\$ 90.00	+
13	WHEEL HOUSING LINER - RH	\$ 159.00	+
14	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 84.00	+
15	LED HEADLIGHT - RH <i>lt</i>	\$ 5,193.00	✓
16	LIFT CYLINDER <i>Ne m</i>	\$ 134.00	+
17	SUNDRIES ?	\$ 300.00	? X
TOTAL SPARE PARTS CHARGES		: \$ 10,409.00	
TOTAL LABOUR CHARGES		: \$ 5,002.00	
GRAND TOTAL		: \$ 15,411.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 31/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant