

**Adjuster Letter/DV not verified.**  
**This claim is to be authorized on the insurer's behalf.**  
**Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.**  
**Click on 'View Letter/DV' to verify the offer.**

**You cannot authorize this offer because**  
**Adjuster Letter/DV not verified.**  
**File to be authorized by your superior.**

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20004582/KEA3Q2  
**Date:** 11/12/2020

### REFERENCE

|                                                        |                               |                        |
|--------------------------------------------------------|-------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 2100472913         |                        |
| Claimant Vehicle No : SLJ684G                          | Insured Vehicle No : SLD7327Z |                        |
| Date of Loss: 25/03/2020                               | Nature of Claim: TP           | Claim No: 0260218746SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |               |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No:                     | SLJ684G                           | Engine No:  | 1NZR431715    |
| Make & Model:               | TOYOTA SIENTA, 1.5 HYBRID (A)     | Chassis No: | NHP1707056492 |
| Reg. Date:                  | 28/11/2016 (Man. Year: 2016)      | Odometer:   | 56269 km      |
| Colour:                     | Metallic Blue                     |             |               |
| Engine Capacity:            | 1496 cc                           |             |               |
| Market Value/New Car Price: | N/A                               |             |               |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |               |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |     |                          |     |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification:    | No  | Pre-accident Condition:  |     |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/60 R15    | Rear Tyre Size:  | 185/60 R15    |
| Front Left Side:  | Michelin 8 mm | Rear Left Side:  | Michelin 8 mm |
| Front Right Side: | Michelin 8 mm | Rear Right Side: | Michelin 8 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                  | Repairer's      | Adjuster's      | Difference    | Diff %       |
|-------------------------------------------------|-----------------|-----------------|---------------|--------------|
| Parts                                           | 2,915.48        | 2,604.38        | 311.10        | 10.67        |
| Miscellaneous Items                             | 0.00            | 0.00            | 0.00          |              |
| Labour                                          | 1,580.00        | 1,430.00        | 150.00        | 9.49         |
| Paintwork Labour                                | 0.00            | 0.00            | 0.00          |              |
| Towing                                          | 0.00            | 0.00            | 0.00          |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>4,495.48</b> | <b>4,034.38</b> | <b>461.10</b> | <b>10.26</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                 | <b>4,034.39</b> |               |              |
| <b>(S\$)</b>                                    | 4,495.48        | 4,034.39        | 461.09        | 10.26        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 314.68          | 282.41          | 32.27         | 10.25        |
| <b>Nett Amount (S\$)</b>                        | <b>4,810.16</b> | <b>4,316.80</b> | <b>493.36</b> | <b>10.26</b> |
| <b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b> |                 | 420.00          |               |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 8.00            |               |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>4,744.80</b> |               |              |

INSPECTION

Date of Assignment: 26/03/2020

Date Inspected: 27/03/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)

10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT  
Singapore 568047

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | <b>*REAR BUMPER</b>                      | Buckled       | 278.00 FL   | *278.00 FL   |
| 2   | 1   |          | <b>*REAR BUMPER SPONGE</b>               | Not Necessary | 25.60 FL    | *- FL        |
| 3   | 1   |          | <b>*REAR BUMPER CENTRE PAD</b>           | Dented        | 180.70 FL   | *180.70 FL   |
| 4   | 1   |          | <b>*REAR BUMPER LH SIDE PAD</b>          | Dented        | 122.80 FL   | *122.80 FL   |
| 5   | 1   |          | <b>*REAR BUMPER LH SIDE REFLECTOR</b>    | Cracked       | 56.90 FL    | *56.90 FL    |
| 6   | 1   |          | <b>*REAR BUMPER LH SIDE RETAINER</b>     | Distorted     | 92.33 FL    | *92.33 FL    |
| 7   | 8   |          | <b>*REAR BUMPER CLIPS</b>                | Necessary     | 28.00 FL    | *28.00 FL    |
| 8   | 1   |          | <b>*REAR TAILGATE</b>                    | Bent          | 1,076.00 FL | *1,076.00 FL |
| 9   | 1   |          | <b>*TAILGATE INNER LOCK</b>              | Not Necessary | 389.20 FL   | *- FL        |
| 10  | 1   |          | <b>*TAILGATE INNER RUBBER</b>            | Cut           | 325.70 FL   | *325.70 FL   |
| 11  | 1   |          | <b>*TAILGATE LOGO</b>                    | Necessary     | 75.25 FL    | *75.25 FL    |
| 12  | 1   |          | <b>*TAILGATE WINDSCREEN MOULDING</b>     | Necessary     | 82.90 FL    | *82.90 FL    |
| 13  | 1   |          | <b>*TAILGATE LH REFLECTOR</b>            | Cut           | 104.00 FL   | *104.00 FL   |
| 14  | 1   |          | <b>*LH TAILLAMP</b>                      | Cut           | 327.00 FL   | *327.00 FL   |
| 15  | 1   |          | <b>*REAR END PANEL</b>                   | Dented        | 374.00 FL   | *374.00 FL   |
| 16  | 1   |          | <b>*REAR END PANEL INNER TOP GARNISH</b> | Mtg Distorted | 232.00 FL   | *232.00 FL   |
| 17  | 1   |          | <b>*TAILGATE EMBLEM (HYBRID)</b>         | Necessary     | 63.60 FL    | *63.60 FL    |
| 18  | 1   |          | <b>*TAILGATE WINDSCREEN GLASS GUM</b>    | Necessary     | 40.00 FS    | *40.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>3,873.98</b> | <b>3,459.18</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$)</b> | 958.50          | 854.80          |
| <b>Total Parts (\$)</b>                                  | <b>2,915.48</b> | <b>2,604.38</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                             | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                                                                                                         |          |                 |                 |
| 1                              | REMOVE AND REFIX REAR WINDSCREEN GLASS                                                                                                                  | New      | 120.00          | 120.00          |
| 2                              | REMOVE & REFIX REAR BUMPER & ATTACHMENTS TAILGATE & ATTACHMENTS ,CUT ,WELD & RENEW REAR END PANEL ,KNOCK & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME | New      | 750.00          | 600.00          |
| 3                              | PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,REAR END PANEL ,REAR LH FENDER & ALL AFFECTED AREAS                                                              | New      | 600.00          | 600.00          |
| 4                              | REMOVE & REFIX REVERSE CAMERA ,RESET & REALIGN THE SAME                                                                                                 | New      | 50.00           | 50.00           |
| 5                              | RUSTPROOFING                                                                                                                                            | New      | 60.00           | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                         |          | <b>1,580.00</b> | <b>1,430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >