

KIANG MOTOR

Block 25 Kaki Bukit Road 4 #08-26 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526

26th March 2020

LOH SIEW HARE
25 KAKI BUKIT ROAD4
08-26 SYNERGY @KB
Singapore 417800

TP Chian.
Khanchan.

GP71120159.

Accident date: 25th MARCH 2020

SMC4206C

Estimated repair cost for vehicle no: ~~SMC4206C~~ Honda Vezel ' 2018

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$952.10	✓
2	1	Rear boot lid emble logo <i>3 New</i>		\$55.00	✓
3	1	Rear boot lid Vezel logo		\$38.10	✓
4	2	Rear Boot Lid side reflector <i>RH cracked</i>	\$385.00	\$770.00	385
5	1	Rear boot lid inner rubber <i>ut</i>		\$237.00	✓
6	1	Rear Boot Lid Inner Lock <i>HE new</i>		\$284.20	X
7	1	Rear Boot Lid Number Plate <i>3 New</i>		\$50.00	X
8	2	Rear Boot Lid Number Plate Lamp <i>3 New</i>	\$61.10	\$122.20	X
9	1	Rear Boot Lid center moulding <i>cracked</i>		\$320.80	✓
10	10	Rear Boot Lid Inner Trim board clips <i>3 New</i>	\$5.00	\$50.00	X
11	1	Rear Boot Lid Inner Trim board		\$425.00	X
12	2	Rear tail lamp <i>RH Smashed</i>	\$405.00	\$810.00	405
13	8	Rear Tail Lamp Clips <i>new</i>	\$6.50	\$52.00	10
14	2	tail lamp inner lower panel -RH <i>cracked</i>	\$285.00	\$570.00	285
15	1	Rear Bumper <i>Distorted</i>		\$885.00	✓
16	8	Rear Bumper Clips <i>new</i>	\$6.50	\$52.00	30
17	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$300.00	X 200(SN)
18	2	Rear Bumper Bracket <i>RH and</i>	\$131.20	\$262.40	58
19	2	Rear Bumper Side Reflector <i>RH cut</i>	\$83.10	\$166.20	83.10
20	1	Rear windscreen moulding <i>new</i>		\$158.00	✓
21	1	Rear Fender- RH <i>Distorted</i>		\$972.40	✓
22	1	rear fender inner cowling -RH <i>new</i>		\$288.00	103
23	1	Rear Fender Inner Trim Board-RH <i>new</i>		\$388.00	✓
24	10	Rear Fender Inner Trim Board Clips <i>new</i>	\$6.50	\$65.00	30
25	1	rear fender mud -shiled -RH <i>3 New</i>		\$112.10	X
26	1	rear fender mud shiled clips <i>new</i>	\$12.90	\$12.90	X
27	1	rear fender Glass -RH <i>new</i>		\$552.00	✓
28	1	end panel <i>Dented</i>		\$451.00	✓
29	1	end panel top garnish <i>new</i>		\$215.00	X
30	1	Rear rim-RH <i>new</i>		\$450.00	X
31	1	Rear spare tire panel lower cover <i>3 New</i>		\$428.00	X
32	1	Rear spare tire panel sealant <i>3 New</i>		\$200.00	X
33	1	Rear Exhaust alumimium cover <i>new</i>		\$112.00	X

Rear RH Bumper Sponge *cracked* 102.60 ✓ Subtotal :-

\$10,806.40

Rear RH Bumper Side Cover *cracked* 115 ✓

6737.50 SN.200

Rear RH Fender Air Grille *cracked* 121.40 ✓

5380

Labour charges

To remove & refit cushion

~~\$120.00~~ 60

To remove & refit reverse sensor

~~\$120.00~~ 50

to remove & refit rear windscreen

~~\$150.00~~ 120

Gum

~~\$50.00~~ ✓

TO remove & refit rear fender glass -RH

~~\$120.00~~ 60

Gum

~~\$50.00~~ 30

To check wiring

~~\$80.00~~ 30

Wheel alignment (computer)

2980

~~\$120.00~~ X

Tuff kote

~~\$120.00~~ 80

Panel beating

\$ 1600 1200

Spray painting

\$ 1500 1200

Subtotal :- \$3,310.00

Total:- \$14,116.40

total 8870

L/S: 6.8K

09 Days.

6.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: