

Premium Automobiles

55 Ubi Road 1 Singapore 408699

Tel 6366 2323 Fax 6841 1183

Email: Nora.khai@premiumauto.com.sg : claims@premiumauto.com.sg

WIP : 33977

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0331/2020/NS
Date : 26-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

14619.60

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Roro Dewi Mashita Binti Mamat
Address : 15 Maida Vale
Singapore 798690
Telephone : HP +65 90287743
Type of Claim : Own Damage Claim
Policy No. : 2100473271-03
Vehicle No : **SLD 8595 J**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Jun-16
Engine No : CNC 168468
Chassis No : WAUZZZ8R5GA141796
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Mar-20
Place of Accident : 15 Maida Vale

Premium Automobiles

Telefax

Estimated Labour Charges for Accident Vehicle. SLD 8595 J

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	✓
2	To remove and reinstall lhs rear back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays	S/N \$ 1,400.00	X
3	To dismantle and renew lhs front door and lhs rear door. To cut out and weld lhs sill pabel. Re-organise crash management components. Reinstall all parts removed.	\$ 4,800.00	1500
4	To respray lhs front door, lhs rear door, door covers, lhs sill panel and door entrances. To carry out stone chip treatment and joint sealer works.	\$ 4,600.00	2050. 3x550 = 1650 Door Cover x 2 = 200 x 2 = 400 2050
5	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,832.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 8595 J

S/N	Parts Description	Damage Parts & Prices		
		S/Nett	Remarks	
1	FRONT DOOR - LH <i>Dented</i>	\$	2,972.00 ✓	2377.60
2	FRONT DOOR ATTACHMENT PARTS ?	NN \$	121.00 ? X	
3	FRONT DOOR OUTER SEAL - LH <i>new</i>	NEC \$	193.00 ✓	154.40
4	BONDING AGENT ?	NEC \$	46.00 ? ✓	36.72
5	CLEANING SOLUTION ?	NEC \$	64.00 ? ✓	51.20
6	FRONT DOOR CATCH <i>new</i>	\$	137.00 +	
7	FRONT DOOR COVER - LH <i>reld</i>	\$	482.00 ✓	385.20
8	REAR DOOR - LH <i>Distorted</i>	\$	2,972.00 ✓	2377.60
9	REAR DOOR OUTER SEAL - LH <i>new</i>	NEC \$	193.00 ✓	154.40
10	BONDING AGENT ?	NEC \$	46.00 ? ✓	36.72
11	CLEANING SOLUTION ?	NEC \$	64.00 ? ✓	51.20
12	STONE CHIP PROTECTION FILM - LH INNER <i>new</i>	\$	73.00 ✓	58.40
13	REAR DOOR ATTACHMENT PARTS ?	NN \$	117.00 ? X	
14	REAR DOOR CATCH <i>not new</i>	\$	137.00 +	
15	REAR DOOR HINGE - LH UPPER / LOWER <i>new</i>	2 \$	285.00 +	
16	SILL PANEL SEAL - LH ?	NEC \$	209.00 ? ✓	167.20
17	INNER DOOR SEAL <i>new</i>	\$	193.00 +	
18	REAR DOOR COVER - LH <i>Missing</i>	\$	385.00 ✓	308.00
19	SILL PANEL - LH <i>Regi</i>	\$	2,031.00 +	
20	SILL TRIM STRIP - LH REAR <i>new</i>	\$	135.00 ? ✓	108.00
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 10,855.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408690
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 8595 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	REAR ALUMINIUM RIM - LH <i>ut</i>	S	944.00 ✓ 754.80
22	UNDERBODY TRIM - LH <i>ok</i>	S	315.00 ✓ 252.00
23	REAR WHEEL HOUSING LINER - LH <i>neu</i>	S	248.00 ✗
24	WHEEL HOUSING LINER ATTACHMENT PARTS <i>neu</i>	S	98.00 ✗
25	ACRYLIC SEALANT <i>2</i>	S/N S	180.00 ✗
26	CAVITY WAX <i>ok</i>	S/N S	140.00 ✗
27	STONE CHIP	S/N S	180.00 ✗
28	SUNDRIES <i>?</i>	NEC S	400.00 ✓ 3.36

TOTAL SPARE PARTS CHARGES	:	\$ 13,360.00
TOTAL LABOUR CHARGES	:	\$ 11,832.00
GRAND TOTAL	:	\$ 25,192.00

All charges are not inclusive of GST

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

28,898.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Telefax

Name

:

Adrian

Surveyed Date

:

27/03/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 27 Days.

29 Days.

H.S.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

:

This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

1100, Beach Road, Singapore 400899

Tel: 6543 1000 Fax: 6543 1188

Supplementary Estimate 1

Est. Ref. No. 18-8902271-0

APC Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-15 APC Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PAPO/0331/2020/11

Date

13 May 20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

50D B5951

Model No

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labour:

1	To remove and re-install the B pillar cover trim to facilitate B pillar repair. inclusive of paint belt	1/1	480 ✓
---	---	-----	-------

TOTAL

480.00

Adrian Ling
13/5/20
[Signature]

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No: 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0331/2020/N5

Date

13-May-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLD 8595 J

Model No

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Sill trim strip for front door entrance LHS <i>see ✓</i>	\$ 226.00	180.80
---	--	-----------	--------

Labours

1	To repair lhs sill panel and lhs B-pillar.	\$ 1,000.00	<i>✓</i>
2	To respray lhs sill panel and lhs B-pillar.	\$ 2,000.00	<i>1100</i>

TOTAL

\$ 3,226.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

For Premium Automobiles Pte Ltd

Rahul
13/05/2020

extra 3 days

Authorised Signature

Subject to

insurance approval