

| | | | | | |
|---|----|---|------------|-----------------------|-------|
| BOOTLID COMFORT LOGO & TEL NO. STICKER <i>Nec</i> | SN | 1 | \$16.60 | \$16.60 | ✓ |
| BOOTLID ADVERTISEMENT LOGO <i>Nec</i> | SN | 1 | \$100.00 | \$100.00 | ✓ |
| REAR NO. PLATE <i>NH</i> | SN | 1 | \$25.00 | \$25.00 | X |
| REAR BUMPER RESERVE SENSOR <i>Don</i> | SN | 1 | \$118.00 | \$118.00 | ✓ |
| REAR BUMPER ADVERTISEMENT LOGO <i>NF</i> | SN | 1 | \$50.00 | \$50.00 | X |
| REAR FENDER ADVERTISEMENT LOGO (LH/RH) <i>Nec</i> | SN | 2 | \$100.00 | \$200.00 | ✓ |
| SUB TOTAL | | | | \$509.60 | |
| <i>484.60</i> | | | | | |
| Labour Charge | | | | | |
| Panel Beating | | 1 | \$1,600.00 | \$1,600.00 | 800/- |
| Spray Painting Charge | | 1 | \$1,400.00 | \$1,400.00 | 800/- |
| Wiring Charge | | 1 | \$80.00 | \$80.00 | 30/- |
| Tuff Kote | | 1 | \$120.00 | \$120.00 | 40/- |
| Towing Charge | | 1 | \$80.00 | \$80.00 | NH |
| Remove/Refix Reverse Sensor | | 1 | \$120.00 | \$120.00 | 40/- |
| Remove/Refix Exhaust Pipe | | 1 | \$80.00 | \$80.00 | 60/- |
| TOTAL LABOUR | | | | \$3,480.00 | |
| ESTIMATE TOTAL | | | | \$ 22,762.24 | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

27/03/2020 @ 1645hr
 NH Antenna
 2/3mm @ 6 days.

10528.12
 Supp 1737.12
 12265.24
 2/S 9800/-

[Signature]
 njan

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 28-Mar-20

MODEL: HYUNDAI I40

VEHICLE NO.: SHD 6899T (S)

INSURANCE: Tolco

| DESCRIPTION | QTY | LIST PRICE | AMOUNT |
|----------------------------|-----|-------------------|--------|
| REAR FENDER <i>Denture</i> | | \$2,171.40 | ✓ |
| | | | |
| SUB TOTAL | | \$2,171.40 | |
| LESS 20% | | \$434.28 | |
| DISCOUNTED TOTAL | | \$1,737.12 | |
| | | | |
| | | | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Signature

2 kt Auto

Signature