



南方摩哆

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

26th March 2020

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block
MND Complex
Singapore (069110)

Dear Sirs,

Stew (LKK) ML
27/3/20, 4.00pm
3 dys
P/P
By BCL sy

RE: Cost of repair to Kawasaki KLE650E – VCR8480

1pc of Front Fork RH / <i>BT</i>	S\$ 880.00
1pc of Front Mudguard / <i>BR</i>	385.00
1pc of Front Brake Disc RH / <i>CNT</i>	950.00
1pc of Sport Light / <i>BR</i>	320.00
1pc of Front Sport Rim / <i>CNT/ST</i>	1,350.00
1pc of Front Brake Plate Caliper <i>X</i>	680.00
1pc of Centre Fairing Cap / <i>CNT (center cluster)</i>	166.00
1pc of Radiator / <i>DD</i>	845.00
1pc of Water Pipe / <i>CR4</i>	45.00
1pc of Lower Cowling / <i>BR</i>	350.00
1pc of Horn / <i>BR</i>	75.00
1pc of Mirror / <i>CNT (LH)</i>	260.00
1pc of Handle Bar / <i>BT</i>	240.00
1pc of Hand Guard / <i>CNT</i>	340.00
1pc of Windscreen / <i>CNT</i>	320.00
1pc of Centre Fairing LH / <i>BR</i>	560.00
1pc of Fuel Tank Side Plate <i>X</i>	290.00
1pc of Body Olider (<i>modify LH</i>) / <i>BT</i>	160.00
1pc of Footrest Bracket / <i>BR</i>	220.00
1pc of Front Footrest / <i>BR</i>	85.00
1pc of Gear Lever / <i>CNT</i>	160.00
1pc of Front Fairing / <i>CNT</i>	430.00
1pc of Magneto Cover / <i>CNT</i>	390.00
1pc of GIVI E450 Box / <i>CNT</i>	180.00

9,681.00

Less 10% 968.10

Nett 8,712.90

Transport 40.00 /

Gasket 25.00 / *ML*

Engine Oil 60.00 *30 /*

Coolant 35.00 *20 /*

Labor 450.00 *350 /*

\$9,322.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours Faithfully,
Southern Motor