



南方摩哆

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

26th March 2020

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block
MND Complex
Singapore (069110)

Dear Sirs,

RE: Cost of repair to Kawasaki KLE650E – VCR8480

1pc of Front Fork RH / BT	S\$ 880.00 ✓
1pc of Front Mudguard / BR	385.00 ✓
1pc of Front Brake Disc RH / CUT	950.00 600 ✓
1pc of Sport Light / BR	320.00 ✓
1pc of Front Sport Rim / CUT / BT	1,350.00 1200 ✓
1pc of Front Brake Plate Caliper X NN	680.00 X
1pc of Centre Fairing Cap / CUT (center cluster)	166.00 ✓
1pc of Radiator / DD	845.00 ✓
1pc of Water Pipe / CR4	45.00 ✓
1pc of Lower Cowling / BR	350.00 ✓
1pc of Horn / BR	75.00 ✓
1pc of Mirror / CUT (LH)	260.00 130 ✓
1pc of Handle Bar / BT	240.00 ✓
1pc of Hand Guard / CUT	340.00 170 ✓
1pc of Windscreen / CUT	320.00 ✓
1pc of Centre Fairing LH / BR	560.00 ✓
1pc of Fuel Tank Side Plate X NN	290.00 X
1pc of Body Olider (modify LH) / BT	160.00 ✓
1pc of Footrest Bracket / BR	220.00 ✓
1pc of Front Footrest / BR	85.00 ✓
1pc of Gear Lever / CUT	160.00 ✓
1pc of Front Fairing / CUT	430.00 ✓
1pc of Magneto Cover / CUT	390.00 ✓
1pc of GIVI E450 Box / CUT	180.00 ✓

9,681.00	7911
Less 10%	-10%
968.10	7119.90
Nett	8,712.90
Transport	40.00 /
Gasket	25.00 / MI
Engine Oil	60.00 30 /
Coolant	35.00 20 /
Labor	450.00 350 /
<u>\$9,322.90</u>	465

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours Faithfully,
Southern Motor

P - 7119.90
L - 465
7584.90

L/S - 6067.92
= 6050