

Kt

Date : 25 / 03 / 2020

ESTIMATE COSTS OF REPAIR

Mr Low Lee Tick
C/o 160 Sin Ming Drive
05-09 Sin Ming Auto City
Singapore 575722

Not Authorised
61 Days @ 13,900/-
Returning After Paint
9 days

Dear Sir / Madam,

Vehicle no. : SLR 2000 A - Toyota Vellfire 2.5
Accident date : 25 / 03 / 2020

Quantity	Descriptions	Amounts
1	1 pc rear bumper 1380	CRMS 2,240.00 ✓
2	1 pc o/s rear bumper side retainer 1 86.20	S D11 176.00 ✓
3	1 pc o/s rear bumper side retainer 2 86.20	S D11 176.00 ✓
4	1 pc o/s rear bumper side cover	Bml S Rd 368.00 ✓
5	1 pc o/s rear bumper reflector	S Bm 128.00 ✓
6	1 pc rear bumper tow cover	S Rm 64.00 X
7	1 pc o/s rear bumper top cover	S D11 438.75 X
8	2 pcs rear bumper clip 1 @ 4.80	S Rm 9.60 ✓
9	1 pc rear weather strip	S Rm 448.00 X
10	1 pc o/s rear fender 1280	Bj S 1,920.00 ✓
11	1 pc o/s rear fender inner garnish	S Rm 1,644.00 X
12	1 pc o/s rear fender quarter glass molding	S Rm 108.00 ✓
13	1 pc o/s rear fender low protector	S D11 352.00 ✓
14	1 pc o/s rear sliding door 2080	Bj S 3,040.00 ✓
15	1 pc o/s rear sliding door inner lock	S Rm 1,120.00 X
16	1 pc o/s rear sliding door protector 822-60	Null/warp 944.00 ✓
17	1 pc o/s rear sliding door rubber	S Rm 528.00 X
18	1 pc o/s rear sliding door regulate gear	S Bj 304.00 ✓
19	1 pc o/s rear sliding door regulate gear motor	S Tm 896.00 ✓
20	1 pc o/s rear sliding door centre rail	S Rm 480.00 X
21	1 pc o/s rear sliding door auto motor	Dist S Rm 2,640.00 ✓
22	1 pc o/s rear sliding door glass outer molding	S Rm 320.00 X
23	1 pc o/s rear sliding door inner trim	S Rm 1,216.00 X
24	1 pc o/s rear sliding door top roller	S Rm 144.00 X
25	1 pc o/s rear sliding door bottom roller	S Rm 224.00 X
26	1 pc o/s rear sliding door centre roller	S Rm 256.00 X
27	2 pcs o/s rear sliding door rail 1 @ 208.00 (top & bottom)	S Rm 416.00 X
28	2 pcs rear lower arm 1 @ 640.00 043P	Dist S 1,280.00 ✓
29	1 pc o/s rear upper arm	Sen S Bj 688.00 2X
	Balance C/FD	S 22,568.35

H C AUTO PTE LTD

Block 20 Sector A Sin Ming Ind. Est. # 01-20 Singapore 575678

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 20082 0153N

Balance B/FD (SLR 2000 A)

S 22,568.35

- | | | | |
|----|------|------------------------------------|------|
| 30 | 1 pc | o/s rear knuckle arm | 842. |
| 31 | 1 pc | o/s rear knuckle arm bearing | 405 |
| 32 | 1 pc | o/s rear trailing arm | |
| 33 | 1 pc | o/s rear wheel hub bearing | 625 |
| 34 | 1 pc | o/s rear shock absorber | |
| 35 | 1 pc | o/s rear bumper lower side garnish | |

\$	BM	1,056.00	✓
\$	M	637.00	✓
\$	P	480.00	X
\$	BM	960.00	✓
\$	P	256.00	X
\$	CM	83.50	✓

Less 25%

S 26,040.85

S 6,510.21

S 19,530.64

- | | | | |
|----|-------|---|-----|
| 36 | 1 pc | rear bumper lower lip | |
| 37 | 1 set | rear bumper reverse sensor | |
| 38 | 1 pc | o/s rear quarter glass inner seal | |
| 39 | 1 pc | o/s rear quarter glass inner gum | |
| 40 | 1 pc | o/s rear wheel rim | P-1 |
| 41 | 1 pc | o/s rear wheel tyre (Michelin 225/35ZR20) | |
| 42 | 1 pc | rear end panel seal | |

CM	\$	2,500.00	sn	✓ 1800sn
M	\$	2,048.00	sn	X
M	\$	60.00	sn	30sn
M	\$	60.00	sn	40sn
Adl 1st	\$	2,800.00	sn	✓ 800sn
P	\$	580.00	sn	X
P	\$	256.00	sn	30sn
\$		27,834.64		

- Labour charges
- To putty and spray painting
- To check wiring
- To re-seal anti rust
- Remove and refix rear undercarriage
- To check wheel alignment
- To transfer o/s rear door
- Remove and refix rear quarter glass
- Remove and refix reverse sensor
- Remove and refix cushion seat, garnish, carpet & etc.

\$	2,000.00	900
\$	1,600.00	1200
\$	160.00	20
\$	250.00	60
\$	450.00	180
\$	100.00	60
\$	160.00	80
\$	320.00	80
\$	100.00	50
\$	450.00	120

Plus : 7% GST

Grand total

\$ 33,424.64

\$ 2,339.72

\$ 35,764.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged By Repairer

Signature:

Date:

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 27 / 03 / 2020

RE : Supplementary

Mr Low Lee Tick

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SLR 2000 A - Toyota Vellfire 2.5
Accident date : 25 / 03 / 2020

Quantity	Descriptions	Amount (S\$)
1	1 pc aircon blower motor assy	<i>mycm</i> \$ 1,216.00 ✓
2	1 pc o/s sliding door soundproffing	<i>mn</i> \$ 250.00 <i>150sn</i>
		\$ 1,466.00
	Less 25%	\$ 366.50
		\$ 1,099.50
3	1 pc coolant	<i>mn</i> \$ 120.00 <i>sn</i> X
		\$ 1,219.50
	coating	\$ <i>mn</i> 600.00 X
	To refill aircon gas	\$ 120.00 <i>100%</i>
		\$ 1,939.50
	Plus : 7% GST	\$ 135.77
	Grand total	\$ 2,075.27