

No:

MON TUE WED THU FRI SAT SUN

TP FWD Shirley.

SFF1134M.

Toyota Wish 1794

JTDER12WS03001S17

Rear Bumper torn	545	✓	
Rear Bumper Clips. New	30	✓	
Rear Bumper Side Holder LH. New	58	✓	
Reverse Sensor New	280(SW)	X	1105
Taillamp LH Lt	472	✓	82875
Rear End Panel Repair	597	X	

Panel Beating	600	250.	
Spray Painting	700	400.	
Wiring.	50	30	
To undersend	150	80	790
To remove reverse sensor	120	50	
To remove upholstery.	120	X	

3,276.50

Total: 1818.75

H/S: 1.2k

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ABC