



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CENTRAL NARCOTICS BUREAU

Ref : CS/CNB18012177/R1qbe2

CORPORATE SERVICES DIVISION BLK B, POLICE
CANTONMENT COMPLEX 393 NEW BRIDGE
ROAD SINGAPORE 088763

Date : 14-08-2018



ATTN : MUHAMMAD ASYRAF

Code : CNB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 9124L	Veh. Inspected	SLP 4212C
Policy No.	HOMCNBEC118300637	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MUHAMMAD ASYRAF	Assign Date	29/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS 1.5E A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3002010285	Colour	GREY
Odometer	101561	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	BRIDGESTONE	5 mm
L/H Front Tyre	195/50 R16	BRIDGESTONE	5 mm
R/H Rear Tyre	195/50 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	195/50 R16	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/06/2018	Inspection Date	09/07/2018
Survey held at	74 KIAN TECK RD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 4212C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	504.90	504.90
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	323.30	-
2	REAR BUMPER SIDE RETAINERS @\$116.30	SERVICEABLE	232.60	-
2	REAR BUMPER SIDE HOLDER @\$22.30	SERVICEABLE	44.60	-
1	N/S REAR BUMPER REFLECTORS	SERVICEABLE	130.50	-
10	REAR BUMPER CLIPS @\$4.30	NECESSARY	43.00	43.00
2	REAR BUMPER SPLASHIED COVER @\$57.50	SERVICEABLE	115.00	-
1	REAR END PANEL	SERVICEABLE	694.70	-
1	REAR END PANEL INNER TRIM	SERVICEABLE	234.30	-
3	REAR END PANEL INNER TRIM CLIPS @\$4.30	SERVICEABLE	12.90	-
	LESS 25% DISCOUNT		-583.95	-136.97
			1,751.85	410.93
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	500.00	-
			500.00	-
<u>LABOUR</u>				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR AND SIMULATON TEST.		150.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	60.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	160.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		700.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.00	200.00
			1,670.00	460.00
GRAND TOTAL			3,921.85	870.93
RECOMMENDED COST OF REPAIRS				870.93

Report Ref No. CS/CNB18012177/R1qbe2

Report Ref No. CS/CNB18012177/R1qbe2



A handwritten signature in black ink, appearing to read 'MRB'.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to read 'A.L.P.'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLP 4212C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLP 4212C

RE-INSPECTION

