



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1570X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LHR DOOR (WCP)	DENTED	550.00	550.00
1	LHR DOOR HANDLE (WCP)	CUT	33.00	33.00
1	LHR DOOR HANDLE KNOB (WCP)	CUT	18.00	18.00
1	LHR DOOR PROTECTOR (WCP)	CUT	70.00	70.00
1	LHR FENDER (WCP)	DENTED	650.00	650.00
1	LHR FENDER ARCH (WCP)	CUT	40.00	40.00
1	LHR PETROL OUTER COVER (WCP)	TO REPAIR SEE LABOUR	45.00	-
1	LHR QUATOR GLASS (WCP)	CUT	326.30	326.30
1	REAR BUMPER (WCP)	CRUSHED	290.00	290.00
1	REAR BUMPER LOWER (WCP)	CUT	160.00	160.00
1	REAR BUMPER SIDE RETAINER LH (WCP)	BROKEN	15.00	15.00
15	REAR BUMPER CLIPS (WCP)	NECESSARY	15.00	15.00
1	LHR TAIL LAMP (WCP)	CUT	370.00	370.00
1	TYRE (NPA)	NOT NECESSARY	-	-
1	SPORT RIM (NPA)	CUT	-	-
	COST PLUS 10% DISCOUNT		258.23	253.73
			2,840.53	2,791.03
<b><u>LABOUR</u></b>				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS, ETC, REMOVE, REINSTALL DAMAGE PARTS, TEST AND RETIFY FOR PROPER FUNCTIONING.		100.00	80.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		100.00	80.00
	TO DISMANTLE AND TRANSFER LHR DOOR FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR.		300.00	120.00
	TO REMOVE AND REINSTALL CUSHIONS, SEAT, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		380.00	200.00
	TO CUT AND WELD LHR FENDER / KNOCK AND REPAIR LHR FENDER INNER PANEL AND AFFECTED AREA. INCLUSIVE OF THE REPAIR OF LHR PETROL OUTER COVER.		850.00	850.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINT LHR DOOR, LHR FENDER, LHR FENDER INNER PANEL, REAR BUMPER AND AFFECTED AREA.		1,200.00	800.00
			2,930.00	2,130.00
<b>GRAND TOTAL</b>			<b>5,770.53</b>	<b>4,921.03</b>

<b>RECOMMENDED COST OF REPAIR SUM</b>			<b>4,200.00</b>
<b>LESS EXCESS</b>			<b>-1,500.00</b>
<b>NETT LIABILITY</b>			<b>2,700.00</b>

Report Ref No. CS/AWA20004606/Evd3e2

**CHEN TSUE YEE**

Automotive Assessor

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.