



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA20004606/Evd3e2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 29-05-2020



Code : AWA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLE 1570X
Policy No.	AVPCSB0316961903	Coverage (\$)	0.00
Claim No.	NSV2000130/PC	Excess (\$)	1,500.00
Assign From	STELLA GOH	Assign Date	27/03/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI TUCSON	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHJ3813MHU273606	Colour	BLUE
Odometer	52708	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	PIRELLI	6 mm
L/H Front Tyre	225/55 R18	PIRELLI	6 mm
R/H Rear Tyre	225/55 R18	PIRELLI	6 mm
L/H Rear Tyre	225/55 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/03/2020	Inspection Date	06/04/2020
Survey held at	NO : 320 UBI ROAD 3		
Repairer	WAH HONG & CREDIT PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$68,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------