



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ODVehicle No. : SLE1570XMake & Model : HYUNDAI TUCONYear of Manufacture : 2016Chassis No. : KMHJ3813MHU273606Ins Company : ALLIED WORLD

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 22/03/2020Time of Accident : 19:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Parts (a) Cost / List Price Items \$ 2,582.30Plus/Less 10% \$ 258.23Total of Cost / List \$ 2,840.53(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 2,840.53Labour (Appendix B) \$ 2,930.00Total Repair Cost \$ 5,770.53

Case Owner : _____

Signature : _____

Contact No _____

68485725 JOHARI

Steve (LKK)

8377 8813

OD - Not Aul (Rend)

Excess - ?

9 days

P/P

My Al sy

6/4/20, 12.00pm

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SLE1570X Case Owner : _____

Make & Model : HYUNDAI TUCSON 2.0 Year Manufacture : 2016

Chassis No : KMHJ3813MHU273606 Engine No : G4NAGU22667

HV : _____ Supplier : _____

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR / <u>OD</u>	1	\$ 550.00				
2	LHRDOOR HANDLE / <u>CH</u>	1	\$ 33.00				
3	LHR DOOR HANDEL KNOB / <u>CH</u>	1	\$ 18.00				
4	LHR DOOR PROTECTOR / <u>CH</u>	1	\$ 70.00				
5	LHR FENDER / <u>DP</u>	1	\$ 650.00				
6	LHR FENDER ARCH / <u>CH</u>	1	\$ 40.00				
7	LHR PETROL OUTER COVER X <u>R</u>	1	\$ 45.00				
8	LHR QUATOR GLASS / <u>CH</u>	1	\$ 326.30				
9	REAR BUMPER / <u>CR</u>	1	\$ 290.00				
10	REAR BUMPER LOWER / <u>CH</u>	1	\$ 160.00				
11	REAR BUMPER SIDE RETAINER LH / <u>SR</u>	1	\$ 15.00				
12	REAR BUMPER CLIP'S / <u>MC</u>	15	\$ 15.00				
13	LHR TAIL LAMP / <u>CH</u>	1	\$ 370.00				
14	TYRE X	1					
15	SPORT RIM (R L H) / <u>CH</u>	1					
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No.	: <u>SLE1570X</u>	Case Owner	: <u>JOHARI</u>
Make & Model	: HYUNDAI TUCSON	Year of Manufacture	: 2016

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

- To display damaged part(s) during **resurvey**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be **resurveyed and** is subject to final approval from Insurance Company

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Acknowledged by Repairer

Signature:

LabourDate: