

Date: 28.03.2020
Vehicle No: SMP4187E
Model: TOYOTA NOAH
Chassis: ZWR800395289-2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SGT15U
Date of Accident: 26.03.2020

Not Authorized
Resurvey B4 paint 3 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER 730.95	1		<i>Bu</i> \$974.60 ✓
2	REAR BUMPER CLIPS 33.00	8	\$5.50	<i>mu</i> \$44.00 ✓
3	REAR TAILGATE 'HYBRID' EMBLEM	1		SVC \$48.70 X
4	REAR TAILGATE	1		REPAIR
5	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,067.30
LESS 20%				-\$213.46
PARTS TOTAL				\$853.84

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR 200.00	1	NEC	<i>fu</i> \$350.00 ✓
S/N TOTAL				\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$500.00 *300l*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$900.00 *450l*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

\$80.00 *50l*

TO DIAGNOSE FAULTY CODE & RESET MEMORY.

NN \$120.00 X

LABOUR TOTAL \$1,600.00

TingAn TOTAL \$2,803.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

