

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34366

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0344/2020/NS
Date : 30-Mar-20

1957.20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SKC 7295 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lim Chee Beng
Address : 33 Amber Road
#18-12
Singapore 439944
Telephone : (HP) +65 97587731
Type of Claim : Third Party Claims
Policy No. : 10704051
Vehicle No : **SLF 9358 K**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 15/6/2016
Engine No : CVN 017094
Chassis No : WAUZZZF45HA020890
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Mar-20
Place of Accident : Still Road South

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 9358 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 9358 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Regis</i>	\$ 2,079.00	+
2	REAR BUMPER FIXING PARTS <i>Ne m</i>	\$ 69.00	+
3	REAR BUMPER SECURING STRIP <i>me</i>	\$ 210.00	168.00
4	REAR BUMPER SPOILER <i>ut</i>	\$ 234.00	187.20
5	REAR LIGHT REFLECTOR - RH REAR <i>Not nec.</i>	\$ 39.00	+
6	LED TAIL LIGHT - RH <i>3</i>	\$ 959.00	+
7	TAIL LIGHT TRIM - RH <i>me</i>	\$ 28.00	+
8	REAR BUMPER CARRIER	\$ 845.00	+
9	REAR BUMPER CARRIER SEAL	2 \$ 26.00	+
10	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 42.00	+
11	REAR PARKING AID SENSOR - INNER / OUTER <i>me</i>	2 TBC	+
12	REAR PARKING AID SEAL RING	4 \$ 14.00	+
13	SUNDRIES	\$ 200.00	+
TOTAL SPARE PARTS CHARGES		:	\$ 4,745.00
TOTAL LABOUR CHARGES		:	\$ 2,502.00
GRAND TOTAL		:	\$ 7,247.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 31/03/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

HS.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant