

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Tellace

WIP : 34363

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0346/2020/NS
Date : 31-Mar-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SGP 6388 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lim Gim Huat
Address : 48 Woodlands Drive 16
#12-53
Singapore 737763
Telephone : (HP) +65 98893028
Type of Claim : Third Party Claims
Policy No. : 1900262904
Vehicle No : **SMR 3522 S**
Model Code : Audi Q3 1.4 TFSI S Tronic
Model / Year : 30/12/2019
Engine No : CZD 885281
Chassis No : WAUZZZF35L1022509
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-20
Place of Accident : Upper Serangoon Rd Toward PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMR 3522 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00 ✓	
2	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00 ✓	
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$	400.00 X	X
4	To dismantle and renew rear bumper, rhs rear door and rhs front door. To repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed. <i>500</i>	\$	3,200.00 <i>1500</i>	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 4,520.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMR 3522 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To respray rear bumper, rhs rear fender, rhs rear door and rhs front door. 580	\$ 4,000.00	2200
6	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	X
7	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 8,992.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 3522 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER X R	\$ 1,397.00	
2	REAR BUMPER FIXING PARTS X NN	TBC	
3	REAR BUMPER SPOILER X NN	\$ 433.00	
4	REAR BUMPER CROSS REINFORCEMENT - CENTRE X NN	\$ 91.00	
5	REAR LIGHT REFLECTOR - RH X NN	\$ 39.00	
6	REAR WHEEL COVER - LH / RH / MC 2	\$ 506.00	404.80 ✓
7	REAR DOOR - RH / DD	\$ 2,512.00	2,009.60 ✓
8	REAR DOOR OUTER SEAL - RH / MC NEC	\$ 127.00	101.60 ✓
9	REAR DOOR ATTACHMENT PARTS ? X NN	\$ 293.00	
10	REAR DOOR CATCH ? X NN	\$ 113.00	
11	DOOR HINGE HALF UPPER PART - RH UPPER ? X NN	\$ 42.00	
12	HINGE HALVES - RH UPPER X NN	\$ 43.00	
13	DOOR HINGE HALF UPPER PART - RH LOWER ? X NN	\$ 45.00	
14	DOOR HINGE HALF LOWER PART - RH LOWER ? X NN	\$ 42.00	
15	REAR DOOR COVER - RH ? ✓ SCR	\$ 242.00	193.20 ✓
16	FRONT DOOR - RH / DD	\$ 2,422.00	1937.60 ✓
17	FRONT DOOR OUTER SEAL - RH / MC NEC	\$ 156.00	124.80 ✓
18	FRONT DOOR ATTACHMENT PARTS ? X NN	\$ 148.00	
19	FRONT DOOR CATCH ? X NN	\$ 113.00	
20	FRONT DOOR COVER - RH ? ✓ SCR	\$ 253.00	202.40 ✓
21	REAR ALUMINIUM RIM - RH X NN	\$ 893.00	
22	SUNDRIES ? ✓ NEC	\$ 300.00	3.36 ✓
TOTAL SPARE PARTS CHARGES		: \$ 10,210.00	
TOTAL LABOUR CHARGES		: \$ 8,992.00	
GRAND TOTAL		: \$ 19,202.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

1/4/70, 2.15pm
Name : Steve CLKK) with R)
Surveyed Date :
Authorised Date : 8322 8813 P/P 10,939.36
Excess Cost :
Liability :
Remarks :
7 dys

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TR/0346/2020/NS

8-May-20

Glory Tan

1 of 1

SMR 3522 5

Audi Q3 1.4 TFSI S Trans

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labours

1	To repair rhs B-pillar.	\$ 800.00 500
2	To respray rhs B-pillar.	\$ 1,000.00 550
3	To respray front door rh and rear door rh handles.	\$ 600.00 200 100

TOTAL

\$ 2,400.00

For Premium Automobiles Pte Ltd

Subject to

insurance

approval

Rail

08/05/2020

Authorised Signature