



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2003632
INV Date 04/05/2020
Reference CC4/EQI20004628/Dea3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 7439D
Insured Veh. SLZ 1804L
Claim No. DM20HO00642-JG
Policy No. DMPPHQ19-004322
Accident Date 25/03/2020
Inspection Date 30/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI20004628/Dea3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 04-05-2020	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLZ 1804L	Veh. Inspected	SMQ 7439D
	Policy No.	DMPPHQ19-004322	Coverage (\$)	0.00
	Claim No.	DM20HO00642-JG	Excess (\$)	0.00
	Assign From	JOEL	Assign Date	27/03/2020
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA CX-3	c.c	1498
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	DK5FW119876	Colour	WHITE
	Odometer	69339	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	BRIDGESTONE	4 mm
	L/H Front Tyre	225/50 R18	BRIDGESTONE	4 mm
	R/H Rear Tyre	225/50 R18	BRIDGESTONE	4 mm
	L/H Rear Tyre	225/50 R18	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/03/2020	Inspection Date	30/03/2020
	Survey held at	RALLY PITSTOP 176 SIN MING DRIVE #04-17 SIN MING AUTO CARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 7439D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED / DENTED	640.90	640.90
5	REAR BUMPER CLIPS @\$3.00	NECESSARY	15.00	15.00
1	REAR END PANEL	NOT NECESSARY	456.90	-
1	REAR REINFORCEMENT	BENT	479.60	479.60
	LESS 10% DISCOUNT		-159.24	-
	LESS 20% DISCOUNT		-	-227.10
			1,433.16	908.40
	<u>LABOUR</u>			
	LABOUR TO DISMANTLE AND CHARGE ALL DAMAGED PARTS.		800.00	400.00
	TO PUTTY AND SPRAY PAINT.		500.00	300.00
	TO DO UNDERCOATING.	NOT NECESSARY	30.00	-
			1,330.00	700.00
	GRAND TOTAL		2,763.16	1,608.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CC4/EQI20004628/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 7439D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 7439D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 7439D

RE-INSPECTION

