

# RALLY PITSTOP

176 Sin Ming Drive  
#04-17 Sin Ming Autocare  
Singapore 575721  
Tel: 64516985  
Email: tar6985@hotmail.com

Date: 30/01/2020

To: Motor Claims Department  
EQ Insurance

RE: Estimate repair cost of SMG7439D

Your Insured: SLZ1804L

Dear Sir/Madam,  
Vehicle No: SMG7439D  
Make Model: Mazda/ CX3  
Date of accident: 26/03/2020

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Rear bumper <i>distorted / Damaged</i>		640.90
5 pcs	Rear bumper clips <i>new</i>	3.00	15.00
1	Rear end panel <i>new</i>		456.90
1	Rear reinforcement <i>new</i>		479.60
	Sub-total before discount		1592.40
	Parts percentage discount 10% <i>20%</i>		159.24
	PARTS TOTAL		1433.16
	LABOUR CHARGES & MISC		
1	Labour to dismantle and change all damaged parts		800.00
2	To putty and spray paint		600.00
3	To do undercoating	450.00	30.00
	LABOUR TOTAL		1330.00
	LABOUR & PARTS TOTAL		2763.16

Regards,  
Terrence Lim

Parts

1135.50

Labour

450.00

30/03/2020 @ 1400hrs

Not Antenna

2/Sum 2 days.

*you*

LKK Auto

*[Signature]*

20% 908.40

1358.40

L/S 1050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: