



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKT13C

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **42657**
Reg No/Reg Date **SKT13C / 10/09/2015**
Date In/Mileage **/ 0**
Chassis No **WDC1569522J150655**
Engine No **13398080039279**
Make/Model **MB/GLA 45 AMG 4MATIC (X156)**
Colour/Trim **026 662 designo mou/ 048 811 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	04/04/2020/ 16:24	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN
POLICY NO/ACC DATE : 8-V0017829-MVA-R001 / 20-03-2020
DRIVE IN: 04-04-2020 / TP CAR NO: GBD4026E (CHINA TAIPING INSURANCE)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

S BPNSUB
SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT
PURCHASE ORDER NO:

A BPILAB
REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT
ASSY COMPONENTS & REFINISH.

A BPIRES
RESPRAY FRONT BUMPER

M RH/F HEADLAMP ? X SVC

M FRT BUMPER ? X SVC

M CT/F IMPACT ABSORBER ? X SVC

M CT/F BASIC MOUNTING FOR BUMPER ? X SVC

M RADIATOR GRILLE STAR ? scr/

M FRT CROSS MEMBER ? X SVC

0.10 380.00 /

X NN 120.00 X

X NN 60.00 X

1440.00 960

1200.00 1000

1.00	2885.53	00.00	2885.53
1.00	1763.08	00.00	1763.08
1.00	142.02	00.00	142.02
1.00	164.95	00.00	164.95
1.00	136.49	00.00	136.49
1.00	333.68	00.00	333.68

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 8,625.75
7% GST on 8625.75 603.80

Authorized signatory and company stamp

Total Payable 9,229.55

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKT13C

Finalization

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Denise

Vehicle & Document Information

WIP No 42657
Reg No/Reg Date SKT13C / 10/09/2015
Date In/Mileage 06/06/2020 / 97374
Chassis No WDC1569522J150655
Engine No 13398080039279
Make/Model MB/GLA 45 AMG 4MATIC (X156)
Colour/Trim 026 662 designo mou/ 048 811 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	
WC000668	Credit	27/07/2020/ 18:25	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE :8-V0017829-MVA-R001 / 20-03-2020
DRIVE IN:04-04-2020 // TP CAR NO:GBD4026E (CHINA TAIPING INSURANCE)
DATE IN/DATE SURVEY:08-04-2020 // DESKTOP SURVEY DENISE TAY
BY/AUTHORIZED ON :PAULINE THAM // 06-04-2020

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT
ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER

X FRT BUMPER

X RADIATOR GRILLE STAR

X FRT BUMPER STICKER

0.10 380.00

960.00

0.07 1000.00

1.00 1763.08 00.00 1763.08

1.00 136.49 00.00 136.49

1.00 289.23 00.00 289.23

THIS IS NOT AN OFFICIAL TAX INVOICE

4 Days

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 4,528.80
7% GST on 4528.80 317.02

Authorized signatory and company stamp

Total Payable 4,845.82

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg





Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKT13C

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **42657**
Reg No/Reg Date **SKT13C / 10/09/2015**
Date In/Mileage **06/06/2020/ 97374**
Chassis No **WDC1569522J150655**
Engine No **13398080039279**
Make/Model **MB/GLA 45 AMG 4MATIC (X156)**
Colour/Trim **026 662 designo mou/ 048 811 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	27/07/2020/ 18:25	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : 8-V0017829-MVA-R001 / 20-03-2020
DRIVE IN: 04-04-2020 // TP CAR NO: GBD4026E (CHINA TAIPING INSURANCE)
DATE IN/DATE SURVEY: 08-04-2020 // DESKTOP SURVEY DENISE TAY
BY/AUTHORIZED ON : PAULINE THAM // 06-04-2020
X FRT BUMPER STICKER **nec** /

1.00	289.23	00.00	289.23
------	--------	-------	--------

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvcclcarriage.com.sg

Confirmed & accepted by

	Nett	289.23
7% GST on	289.23	20.25

Authorized signatory and company stamp

Total Payable 309.48

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg