

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/03/2020
Vehicle Reg. No.:	SHA6937H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	22/10/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU399141	Chassis No:	KMHC851CVLU186632
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,699.08
Miscellaneous Items	11.00
Labour	1,290.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,000.08
+ GST 7.00% (S\$)	210.01
Nett Amount (S\$)	3,210.09

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Mar 2020)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA6937H/27/03/2020 15:34**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Cia-</i>	20.00	0.00	*459.40 FL
2	2		*REAR BUMPER SIDE BRACKET RH/LH <i>xun</i>	20.00	0.00	*111.60 FL
3	10		*REAR BUMPER CLIPS <i>nec-</i>	20.00	0.00	*22.00 FL
4	1		*REAR BUMPER REINFORCEMENT <i>? xun</i>	20.00	0.00	*294.80 FL
5	1		*REAR BUMPER LOWER MOULDING <i>xun</i>	20.00	0.00	*155.00 FL
6	1		*REAR BUMPER CENTRE MOULDING <i>Cut-</i>	20.00	0.00	*451.25 FL
7	1		*BOOTLID CRDI PLATE <i>xun</i>	20.00	0.00	*28.00 FL
8	1		*BOOTLID CRDI H EMBLEM <i>xun</i>	20.00	0.00	*28.00 FL
9	1		*REAR BUMPER TOW COVER <i>xun</i>	20.00	0.00	*98.80 FL
10	1		*REAR BUMPER MAT <i>nec- AA</i>	0	0.00	*50.00 FS
11	1		*REAR NUMBER PLATE /WITH HOLDER <i>xun</i>	0	0.00	*50.00 FS
12	1		*REAR REVERSE SENSOR <i>? nn</i>	0	0.00	*180.00 FS
13	1		*BOOTLID COMFORT STICKER <i>xun</i>	0	0.00	*30.00 FS
14	1		*BOOTLID COMFORT TEL NO. STICKER <i>xun</i>	0	0.00	*30.00 FS
15	1		*BOOTLID APP COMFORT STICKER <i>xun</i>	0	0.00	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,028.85
- List Item Discount on L Items (\$)	329.77
Total Parts (\$)	1,699.08

ComfortDelGro Engineering Pte Ltd/SHA6937H/27/03/2020 15:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	1 OD/TP Case (Insurer)	11.00
Sub Total (\$\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$320 640.00
2	SPRAY PAINTING	New	\$200 450.00
3	TUFF KOTE	New	\$30 60.00
4	CHECK LIGHTING	New	\$50 60.00
5	REMOVE/REFIX REVERSE SENSOR	New	\$60 80.00
Gross Labour Cost (\$\$)			1,290.00

ComfortDelGro Engineering Pte Ltd/SHA6937H/27/03/2020 15:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ram (LKK)
 30/03/2020 1305
 Paraguram@lkkauto.com
 Be a paint photo
 (P/P)
 (2) repair days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: