

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

30/03/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SLE4845J

Veh Model :- HONDA VEZEL 1.5X VCT ABS

Estimate# :- CK420570

Claim # :-

ACC. Date :- 27/03/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	TAILGATE <i>bt</i>	1	PC	1,050.00	1,050.00 ✓
2.	TAILGATE GLASS MOULDING <i>re</i>	1	PC	120.00	120.00 ✓
3.	TAILGATE GARNISH <i>X SVC</i>	1	PC	220.00	220.00 X
4.	TAILGATE LOGO <i>X NN</i>	1	PC	15.40	15.40 X
5.	TAILGATE REFLECTOR RH & LH <i>? X SVC</i>	2	PCS	264.60	529.20 X
6.	TAILGATE EMBLEM - VEZEL <i>re</i>	1	PC	43.00	43.00 ✓
7.	TAILGATE LOCK <i>cm</i>	1	PC	157.00	157.00 ✓
8.	TAILGATE WEATHERSTRIP <i>re</i>	1	PC	96.80	96.80 ✓
9.	TAILGATE INNER TRIM <i>X SVC</i>	1	PC	153.40	153.40 X
10.	TAILLAMP ASSY RH & LH <i>X SVC</i>	2	PCS	441.50	883.00 X
11.	REAR END PANEL <i>Repair</i>	1	PC	441.90	441.90 X
12.	REAR END PANEL TOP COVER <i>X SVC</i>	1	PC	92.30	92.30 X
13.	REAR BUMPER <i>SCA</i>	1	PC	463.70	463.70 ✓
14.	REAR BUMPER BRACKET RH & LH <i>? XSVC</i>	2	PCS	13.90	27.80 X
15.	REAR BUMPER RETAINER RH & LH <i>X SVC</i>	2	PCS	17.50	35.00 X
16.	REAR BUMPER LOWER GARNISH <i>repair</i>	1	PC	190.00	190.00 X
17.	REAR BUMPER CLIPS <i>re</i>	10	PCS	3.50	35.00 ✓

LIST TOTAL S\$

20% DISCOUNT S\$

1965.50 4,553.50
- 393.10 -910.70

11572.40 3,642.80

SPECIAL NET ITEMS :

1.	TAILGATE GLASS SEALANT <i>NEC</i>	1	PC	40.00	40.00 ✓
2.	REAR NUMBER PLATE <i>X NN</i>	1	PC	40.00	40.00 X
3.	REVERSE SENSOR <i>NW</i>	1	SET	200.00	200.00 ✓

SPECIAL NET TOTAL S\$

21288.00 ✓

LABOUR :

TO CUT/WELD REAR END PANEL. KNOCK AND
STRAIGHTEN REAR BODY MEMBER. REMOVE AND
REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL
CONNECTION.

SPRAY PAINT TAILGATE, REAR END PANEL, REAR
BODY MEMBER, REAR BUMPER

REMOVE & REINSTALL TAILGATE GLASS AND CHECK
WATER LEAKAGE

REMOVE & REFIT TAILGATE TRIM BOARD, MECHANISM
AND CHECK LOCKING SYSTEM

REMOVE & REFIT LUGGAGE COMPARTMENT INNER
TRIM, GARNISH

REMOVE & REINSTALL REVERSE SENSOR AND CHECK
FUNCTION

400 800.00 ✓

600 700.00 ✓

120.00 ✓

50.00 ✓

40 60.00 ✓

40 50.00 ✓

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

30/03/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 137986
Veh # :- SLE4845J
Veh Model :- HONDA VEZEL 1.5X VCT ABS
Estimate# :- CK420570
Claim # :-
ACC. Date :- 27/03/20
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	RUST PROOF AFFECTED AREAS			40 60.00
	LABOUR TOTAL S\$			2) 1290.00 1,840.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,762.80

GST @ 7 % 403.40

AMOUNT DUE S\$ 6,166.20

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

1) PARTS 1572.40
2) PAINT 240.00
3) LABOUR 1290.00
3102.40
- 628.48 less 20%
2481.93

Lump Sum @ 2450.00

Please advice. Thank You
BUT NOT.

Rasul
Hp 90010068
5 Days
4/8
30/03/2020 @ 1600
Resy after repair