



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT

Aik Hoe Heng Construction Engineering Works
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : SLL 9999D
Make And Model : Mercedes Benz
CLA-190
Date of Accident : 24 Mar 2020

S/No	Parts	QTY	Unit Price	List Price
1	Front door (R/H) / <i>DO</i>	1		\$ 1,960.00 ✓
2	Front door chrome moulding / <i>BT</i>	1		\$ 285.00 ✓
3	Front door glass / <i>CMT</i>	1		\$ 276.25 ✓
4	Front door outer handle / <i>CMT</i>	1		\$ 389.50 ✓
5	Front door outer handle bracket (R/H) / <i>BR</i>	1		\$ 226.00 ✓
6	Front door inner lock ? Jammed ✓	1		\$ 537.00 384 ✓
7	Front door inner lock cover / <i>CMT</i>	1		\$ 81.30 ✓
8	Front door window regulator ? <i>BT</i> ✓	1		\$ 315.00 ✓
9	Front door window regulator motor ? Jammed ✓	1		\$ 682.00 500 ✓
10	Front door weatherstrip / <i>MC</i>	1		\$ 358.00 280 ✓
11	Front door rivet / <i>MC</i>	1 set		\$ 132.00 <i>30</i> ✓
12	Side view mirror assembly / <i>BR</i>	1		\$ 1,672.00 1253 ✓
13	Rear door (R/H) / <i>DO</i>	1		\$ 1,587.00 ✓
14	Rear door checker X NN	1		\$ 130.00 X
15	Rear door hinge ? ✓ <i>BT</i>	2	\$ 158.00	\$ 316.00 ✓
16	Rear door weatherstrip / <i>MC</i>	1		\$ 480.00 280 ✓
17	Rear door chrome moulding / <i>BT</i>	1		\$ 255.00 ✓
18	Rear door inner lock ? ✓ Jammed	1		\$ 690.00 410 ✓
19	Rear door window regulator ? ✓ <i>BT</i>	1		\$ 336.00 ✓
20	Rear door window regulator motor ? ✓ Jammed	1		\$ 325.00 ✓
21	Rear door rivet / <i>MC</i>	1 set		\$ 130.00 <i>30</i> ✓
22	Rear door fender / <i>DO</i>	1		\$ 2,080.00 ✓
23	Rear bumper / <i>DO</i>	1		\$ 1,642.00 ✓
24	Rear door sensor ? X NN	2	\$ 259.00	\$ 518.00 X
25	Rear wheel rim (R/H) / <i>CMT</i>	1		\$ 1,021.00 700 ✓
26	Rear wheel bearing ? X NN	1		\$ 322.00 X
27	Rear knuckle arm ? X NN	1		\$ 1,530.00 X
28	Rear shock absorber X NN	1		\$ 522.00 X
29	Rear lower arm ? X NN	1		\$ 566.00 X

To be continued page 2



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

Page 2

S/No	Parts	QTY	Unit Price	List Price
30	Rear thrust arm X NN	1	\$	680.00 X
31	Rear upper arm X NN	1	\$	510.00 X
32	Rear strut arm X NN	1	\$	562.00 X
				\$ 21,116.05
Less 10%				\$ 2,111.61
Total				\$ 19,004.44

Special Nett Item

1	Windscreen sealant / Mc	\$	60.00 40/
---	-------------------------	----	-----------

Labour & Misc Charges

To dismantle, replace & panel beating affected parts.	\$	1,200.00 1100/
To spray paint on affected areas.	\$	1,400.00 1800/
To remove & refit rear windscreen glass.	\$	200.00 120/
To remove/refit interior fittings.	\$	250.00 100/
To replace rear under carriage parts.	\$	300.00 ? X
To remove/refit reverse sensors.	\$	80.00 30/
To check wiring.	\$	100.00 /
To check wheel alignment.	\$	100.00 60/
Towing.	\$	100.00 60/

Total \$ 3,790.00

Grand Total : \$ 22,794.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve CLKK 00 - Not Author

Excess - ?

30/3/20, 3.00pm

10 days

L/S

By AL sy