

Allen Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP MSIG
Claim Type: Third Party
Accident Date: 24/03/2020
TP Veh Reg No: EQ180P

Estimate No: ES2090447 ES2090447/WS
Date: 09 Jun 2020
Policy No:
Veh Reg No: GBH5998Y
Make/Model: NISSAN NISSAN NV200
Chassis No: VSKYBAM20U0153530
Engine No:
Reg. Date: 26/07/2018

*Not Authorized
Respray B4 paint
3 days*

Estimate Repair Cost to Vehicle No :GBH5998Y

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT BUMPER	655.20	1 PC	655.20	✓
2 FRONT BUMPER SIDE RETAINER RH	25.40	1 PC	25.40	✓
3 FRONT BUMPER CLIP	5.00	6 PCS	30.00	✓
4 FRONT BUMPER FOG LAMP GARNISH RH	96.80	1 PC	96.80	✓
5 HEADLAMP RH	444.63	1 PC	444.63	✓
6 RH HEADLAMP LOWER GARNISH	368.50	1 PC	368.50	✓
7 FRT RH FENDER INNER SHIELD	188.40	1 PC	188.40	✓
			1,808.93	
		Less 10%	180.89	1,628.04
Special Net				
8 COMPANY STICKER	20.00	2 PC	40.00	✓
9 FRONT BUMPER FOG LAMP RH	321.60	1 PC	321.60	✓
			361.60	361.60
Labour				
10 TO REMOVE AND REFIXD FRT BUMPER ASSY, FOG LAMPS, HEADLAMP AND LOWER COVER, KNOCK AND REPAIR FRT BUMPER REINFORCEMENT, FRT RH FENDER AND RE-ALIGN TO SAME	500.00	1 LA	500.00	400
11 TO PUTTY AND RESPRAY ON FRT RH FENDER, RH HEADLAMP LOWER COVER,	350.00	1 LA	350.00	300
			850.00	850.00
			Total	S\$ 2,839.64
			Add GST @ 7%	198.77
			Total Amount Payable	S\$ 3,038.41

*Parts \$1712.13 ✓
less 10% 171.22
\$1540.91
40 SIN
700
\$2200.91*

For Cheng Hoe Motor Pte Ltd

[Signature]
AUTHORISED SIGNATURE