

HONDA

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Page 1

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLN2021K
Chassis No : JHMRU1830GX202205
Model : HRV LX-SIN CVT YM 2016
Owner's Name : SAUJIT BANDHU
Ins Policy No. :
Date of Accident : 27/3/2020

Document No. : SQT20001372
Date : 27. Mar 2020
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : L15B4532206
Date | Time : 27. Mar 2020 5:43:01 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04636-T7A-310ZZ	PANEL SET,R.RR.OUTSIDE <i>X Svc</i>	1	630.30	25	472.72	33.09	505.81
67510-T7A-300ZZ	PANEL COMPR.RR.DOOR <i>repair</i>	1	935.10	25	701.32	49.09	750.41
67825-T7A-003	TAPER.RR.DOOR SASH <i>new ? XAN</i>	1	20.30	5	19.28	1.35	20.63
75890-T7A-003	TAPE,R.RR.DOOR PROTECTION <i>new</i>	1	24.80	5	23.56	1.65	25.21
42700-T7A-J93	DISK,ALUMINIUM WHEEL <i>SC</i>	1	740.40	5	703.38	49.24	752.62
74410-T7A-J01ZN	PROTECTOR,R.RR.WHEEL ARCH <i>SC</i>	1	173.10	5	164.44	11.51	175.95
91505-TM8-003	CLIP,BUMPER <i>new</i>	14	2.30	5	30.59	2.14	32.73
04715-T7A-900ZZ	FACE,RR.BUMPER <i>repair</i>	1	463.70	5	440.51	30.84	471.35
33505-T7A-J01	REFLECTOR ASSYR.RR. <i>X Svc</i>	1	170.80	5	162.26	11.36	173.62
71593-T9A-J00	SPACER R.RR.BUMPER SIDE <i>new</i>	1	11.50	5	10.92	0.76	11.68
71598-T9A-J00	SPACER L.RR.BUMPER SIDE <i>X Svc</i>	1	11.50	5	10.92	0.76	11.68
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER <i>cut</i>	1	96.50	5	91.67	6.42	98.09
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>? X Svc</i>	1	320.00		320.00	22.40	342.40
Sum Item					3151.57	220.61	3,372.18
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00		140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80
BKBU01R	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	650.00	580	650.00	45.50	695.50

Printed on 27/3/2020 6:01:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 Registration No : SLN2021K
 Chassis No : JHMRU1830GX202205
 Model : HRV LX-SIN CVT YM 2016
 Owner's Name : SAUJIT BANDHU
 Ins Policy No. :
 Date of Accident : 27/3/2020

Document No. : SQT20001372
 Date : 27. Mar 2020
 Customer No. : WZC008
 Svc Advisor : NG SIN HAI
 Engine No : L15B4532206
 Date | Time : 27. Mar 2020 5:43:01 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BM103D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	X	650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT FOR DOOR	1	100.00	X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FENDER	1	100.00	X	100.00	7.00	107.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00	X	650.00	45.50	695.50
BKFE22R	CUT OFF & RENEW RR R FENDER.	1	4000.00	1300	4000.00	280.00	4280.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	3000.00	1560	3000.00	210.00	3210.00
3930					Sum Labor	9530.00	667.10
							10,197.10
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
					Sum Ext. Service	180.00	12.60
							192.60

Survey By
 Date & Time
 Excess
 Status
 Signature

Resul - Hp 90010068
 02/07/2020 @ 1425

5 days

Reay before paint

1030.07

3930.00

4960.07

5 days

Total Amount 12861.57 900.31 13,761.88
 Total (Inclusive of GST) 4960.07 13,761.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items, parts and materials are subject to final approval from the Repairer's Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/3/2020 6:01:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.