



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 1977014696

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM KOK LEONG	Cust No/Name	KCV11790/LIM KOK LEONG
BLK 271B SENGKANG CENTRAL #02-273 SINGAPORE 542271	Reg No/Reg Date	SMN1539D / 26/07/201
Contact No Mobile: 96814577	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AKH002730
	Engine No	3A92UHX9673
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00041	Cash	28/03/2020/ 11:52	QUD	247 / DonBong	52614	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000		RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, REPAIR BOTH FRONT FENDER				1100 <del>2750.00</del>
E PNT88000		REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK				NN X 120.00
A 55900099		TOP UP AIR CON GAS AND CHECK A/CON SYSTEM				NN X 80.00
E PNT98000		PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER AND AFFECTED PORTION				840 <del>2520.00</del>
M SUNDRY		APPLY BODY SEALANT ON AFFECTED PORTION				40 160.00
A 54900099		CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 <del>50.00</del>
M SUNDRY		PERFORM RUST PREVENTION				40 <del>80.00</del>
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY		APPLY BODY SEALANT				NN X 160.00
M SUNDRY		SUPPLY FRONT NUMBER PLATE WITH FRAME				NN X 50.00
M SUNDRY		SUNDRIES				20 <del>50.00</del>
M HINGE, HOOD, LH X SVC			1.00	56.00	00.00	56.00
M HINGE, HOOD, RH X SVC			1.00	56.00	00.00	56.00
M HOOD			1.00	734.00	00.00	734.00
M INSULATOR, HOOD X NN			1.00	177.00	00.00	177.00
M LATCH, HOOD X SVC			1.00	69.00	00.00	69.00
M HEADLAMP ASSY, LH X SVC			1.00	660.00	00.00	660.00
M HEADLAMP ASSY, RH X SVC			1.00	660.00	00.00	660.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
LIM KOK LEONG  BLK 271B SENGKANG CENTRAL #02-273 SINGAPORE 542271  Contact No Mobile: 96814577	Cust No/Name	KCV11790/LIM KOK LEONG
	Reg No/Reg Date	SMN1539D / 26/07/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AKH002730
	Engine No	3A92UHX9673
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	28/03/2020/ 11:52	QUD	247 / DonBong	52614

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GRILLE, RADIATOR <i>cm 9</i>	1.00	554.00	00.00	554.00
M BRACKET, FR BUMPER, LH <i>X SVC</i>	1.00	13.00	00.00	13.00
M BRACKET, FR BUMPER, RH <i>X SVC</i>	1.00	13.00	00.00	13.00
M COVER, HEADLAMP SUPT PANEL <i>X SVC</i>	1.00	62.00	00.00	62.00
M CLIP, FR BUMPER <i>X NN</i>	6.00	4.00	00.00	24.00
M MARK, THREE-DIA <i>na</i>	1.00	69.00	00.00	69.00
M GRILLE, FR UNDER <i>X SVC</i>	1.00	165.00	00.00	165.00
M GARNISH, FR BUMPER, LH <i>X SVC</i>	1.00	127.00	00.00	127.00
M GARNISH, FR BUMPER, RH <i>X SVC</i>	1.00	127.00	00.00	127.00
M PANEL, HEADLAMP SUPPORT, UPR <i>X SVC</i>	1.00	65.00	00.00	65.00
M PANEL ASSY, FR END <i>X SVC</i>	1.00	1055.00	00.00	1055.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: *Rosul*

SURVEYOR SIGNATURE: *Rosul*

DATE: *31/03/2020 @ 1110*

REMARKS: *4 days*

*Resy before paint*

Confirm & accepted by

Nett	10,906.00
7% GST on	10906.00
<b>Total Payable</b>	<b>11,669.42</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.