

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT20001164	Page	1
	300 BEACH ROAD #17-04/07	Date	: 11. Mar 2020		
	THE CONCOURSE	Customer No.	: WZL009		
	SINGAPORE 199555	Svc Advisor	: NG SIN HAI		
Registration No	: SMK2984K	Engine No	: L13B14100580		
Chassis No	: JHMGK3850KS211544	Date Time	: 11. Mar 2020 2:09:20 PM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: LING HWE FUN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/3/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING-OPC-L <i>rel ✓</i>	1	45.00		45.00	3.15	48.15
04711-T5A-J50ZZ	FACE,FR.BUMPER <i>de ✓</i>	1	517.70	25	388.27	27.18	415.45
71190-T5A-J50	BEAM UPPER,L.FR.BUMPER ?	1	28.40	25	21.30	1.49	22.79
71108-T5A-J50	GARNISH,L.FR.BUMPER <i>mis ✓</i>	1	29.70	25	22.27	1.56	23.83
91505-TM8-003	CLIP,BUMPER <i>rel ✓</i>	19	2.30	25	32.77	2.29	35.06
71198-T5A-000	SPACERL.FR.BUMPER <i>rel ✓</i>	1	10.40	25	7.80	0.55	8.35
33150-T5A-J81	HEADLIGHT ASSY,L. <i>unt ✓</i>	1	492.10	25	369.07	25.83	394.90
60261-T5R-A00ZZ	PANEL,L.FR.FENDER <i>Rp ✓</i>	1	408.90	25	306.67	21.47	328.14
60690-T5A-300ZZ	BRACKET COMP,L.FR.FENDER X	1	42.80	25	32.10	2.25	34.35
74150-T5L-T10	FENDER ASSY,L.FR.INNER ?	1	75.60	25	56.70	3.97	60.67
74155-T5A-J00	ENCLOSURE,L.FR.FENDER X	1	18.00	25	13.50	0.95	14.45
04684-T5A-300ZZ	EXTENSION SETL.FR. ?	1	96.80	25	72.60	5.08	77.68
Sum Item					1368.05	95.77	1,463.82
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	✓	180.00	12.60	192.60
BKBH01R	CUT & RENEW EXTENSION AND RENEW DAMAGED PARTS	1	3000.00	1300	3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	1560	2500.00	175.00	2675.00

Printed on 25/3/2020 7:42:48 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555

Registration No : SMK2984K

Chassis No : JHMGK3850KS211544

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : LING HWE FUN

Ins Policy No. :

Date of Accident : 10/3/2020

Document No. : SQT20001164 **Page** 2

Date : 11. Mar 2020

Customer No. : WZL009

Svc Advisor : NG SIN HAI

Engine No : L13B14100580

Date | Time : 11. Mar 2020 2:09:20 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	REMOVE AND RE-SEAL OF OPC PLATE	1	650.00	✓	650.00	45.50	695.50
Sum Labor					6430.00	450.10	6,880.10

Survey By Taufik 97495749.Date & Time 30/4/20 2:11pmExcess - WP

Status _____

Signature [Signature]**Total Amount** 7,798.05 545.87 8,343.92**Total (Inclusive of GST)** **8,343.92**

06 days
Resurvey before paint.
taufik@lkkauto.com
sur@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Printed on 25/3/2020 7:42:48 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.