

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

C03/MS 620004651/UGV3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 52917
 SML 6662H -X
 SLA 892K -X

31/3/20 @ 3pm Informed Ng Chen How, we are pending estimate from repairer.

23/4/20 4/5 @ 2400 confirmed with Alan. (Red \$6745.30, 74%)

23/04/20@10.43am revised to Chen How via Merimen.

Date/Time, File Pass to?

☐

Preli. Report

1) 23/04 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format: MER-TP

Lump Sum / T.B. (\$) 2400)

TOTAL

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

VEHICLE No: SML 6662H

not Authorized
dhan
2/5 @ 2400
3 days.

1PC	FRONT BUMPER	980.50
1PC	FRONT BUMPER SIDE RETAINER N/S	32.50
1SET	FRONT BUMPER CLIPS	
1PC	FRONT BUMPER REINFORCEMENT	
1PC	HEADLAMP N/S	1615.20
1PC	FRONT GRILLE	
1PC	FRONT FENDER N/S	
1PC	FRONT FENDER 'HYBRID' EMBLEM N/S	68.50
1PC	FRONT FENDER INNER SHIELD N/S	
1SET	FRONT FENDER INNER SHIELD CLIPS	
1PC	FRONT WHEEL HUB CAP N/S	
1PC	FRONT LOWER ARM N/S	
1PC	FRONT KNUCKLE ARM N/S	
1PC	FRONT KNUCKLE ARM BEARING N/S	
1PC	FRONT SHOCK ABSORBER N/S	

Boopcar	\$1,250.00	—
cm	\$66.50	—
mm	\$39.00	—
11	\$366.50	X
holder	\$2,880.00	—
11	\$422.30	X
11	\$488.20	X
mm	\$105.00	✓
11	\$122.30	X
11	\$39.00	X
11	\$250.00	X
11	\$392.00	X
11	\$425.30	X
11	\$250.00	X
11	\$399.20	X
	\$7,495.30	

(20%)

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX FRONT UNDERCARRIAGE
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$50.00	X
11	\$120.00	X
11	\$150.00	X
	\$600.00	350
	\$680.00	450
TOTAL	\$9,145.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 27357
201
2188.56
300886
1406.