

N51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

TP FWD.

vic.

ESTIMATE

Repair Code : CLM16166

Date in : 27/03/2020

Vehicle Num. : SLW3520H

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng# : RU31222451/LEB5922462

Contact : 66550005-GRAB 87880039

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER LOWER LID <i>torn</i>	1	381.00	✓ 381.00
FRONT BUMPER LOWER SPOILER <i>wt</i>	1	138.00	✓ 138.00
FRONT ENGINE UNDER COVER <i>wt</i>	1	98.00	✓ 98.00
FRONT LH ABS SENSOR <i>new</i>	1	180.00	X 180.00
FRONT LH FENDER 'HYBRID' EMBLEM <i>new</i>	1	58.00	✓ 58.00
FRONT LH FENDER ARCH GARNISH <i>wt</i>	1	220.00	✓ 220.00
FRONT LH FENDER INNER SHIELD <i>new</i>	1	130.00	X 130.00
FRONT LH KNUCKLE ARM <i>brk</i>	1	390.00	✓ 390.00
FRONT LH KNUCKLE ARM BEARING <i>new</i>	1	181.40	✓ 181.40
FRONT LH LOWER ARM <i>Bent</i>	1	371.00	✓ 371.00
FRONT LH LOWER BALL JOINT <i>bent</i>	1	98.70	✓ 98.70
FRONT LH SHOCK ABSORBER <i>Bent</i>	1	503.00	✓ 503.00
FRONT LH SHOCK ABSORBER TOP MOUNTING <i>new</i>	1	75.00	X 75.00
FRONT LH STABILIZER LINK <i>new</i>	1	60.00	X 60.00
FRONT LH TIE ROD END <i>new</i>	1	80.00	X 80.00
FRONT LH WHEEL HUB CAP <i>cracked</i>	1	198.00	200(SN) 198.00
FRONT LH WHEEL RIM <i>bent</i>	1	765.80	200(SN) 765.80
REAR LH ABS SENSOR <i>new</i>	1	180.00	X 180.00

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Bukit AutoHub
 17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 Email : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 87880039

ESTIMATE

Repair Code : CLM16166

Date in : 27/03/2020

Vehicle Num. : SLW3520H

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng# : RU31222451/LEB5922462

REAR LH DOOR <i>Dented</i>	1	930.60	✓	930.60
REAR LH DOOR BLACK TAPE <i>NA</i>	1	35.00	✓	35.00
REAR LH DOOR MECHANISM LOCK <i>NA</i>	1	210.00	X	210.00
REAR LH DOOR TRANSPARENT STICKER <i>new</i>	1	35.00	✓	35.00
REAR LH DOOR WEATHER STRIP <i>new torn</i>	1	98.00	✓	98.00
REAR LH DOOR WEATHER STRIP (LOWER) <i>torn</i>	1	65.00	✓	65.00
REAR LH DOOR WEATHER STRIP (VERTICAL) <i>Not NA</i>	1	65.00	X	65.00
REAR LH FENDER <i>Repair</i>	1	884.40	X	884.40
REAR LH FENDER ARCH GARNISH <i>LT</i>	1	195.00	✓	195.00
REAR LH FENDER INNER SHIELD <i>torn</i>	1	153.40	✓	153.40
REAR LH SHOCK ABSORBER <i>Best</i>	1	385.00	✓	385.00
REAR LH WHEEL BEARING <i>2nd</i>	1	263.50	✓	263.50
REAR LH WHEEL HUB CAP <i>crack Missing</i>	1	185.00	120(SN)	185.00
REAR LH WHEEL RIM <i>Best</i>	1	813.00	200(SN)	813.00
ROCKER GARNISH LH <i>Rebond</i>	1	377.50	✓	377.50
Reas Axle <i>Best</i>	1	1650	✓	1650

*** This is a computer-generated document which requires no signature.***

page 2

662810 S.N. 640

S 302 48.

N51 AUTOMOTIVE PTE LTD

Bukit AutoHub
 18 Bukit Ave 2
 #17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 87880039

ESTIMATE

Repair Code : CLM16166
 Date in : 27/03/2020
 Vehicle Num. : SLW3520H
 Model : HONDA VEZEL HYBRID 1.5 AUTO
 Chassis/Eng# : RU31222451/LEB5922462

Subtotal before discount		8,803.30
Percentage discount 20%		1,760.66
Sub-total 1		7,042.64
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00 30 50.00
FRONT LH 215/60R16 TYRE <i>Replaced</i>	1	380.00 220(SW) 380.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	40.00 30 40.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00 50.00
REAR LH 215/60R16 TYRE <i>Replaced</i>	1	380.00 220(SW) 380.00
REAR LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	40.00 30 40.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00 30 50.00
ROCKER GARNISH LH CLIPS - SET <i>new</i>	1	50.00 30 50.00
Subtotal before discount		1,040.00
Percentage discount 0%		0.00
Sub-total 2		1,040.00
Parts-total		8,082.64

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30	100.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	220	380.00
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	300	450.00
To road test driving, check and resetting wheel alignments system.	80	140.00

*** This is a computer-generated document which requires no signature.***

51 AUTOMOTIVE PTE LTD

LKK AutoHub
18 Sin Ming Lane #01-08 / Spray Painting #02-27
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
Email : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 87880039

ESTIMATE

Repair Code : CLM16166

Date in : 27/03/2020

Vehicle Num. : SLW3520H

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng# : RU31222451/LEB5922462

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	50	140.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	✓	80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600	1,100.00
To apply anti-rust chemical on repaired and replaced panel.	60	120.00
	2220	
Labour Total		3,710.00
Parts & Labour Total		11,792.64

*** This is a computer-generated document which requires no signature.***

page 4

Admin Lj
30/03/20 Lump Sum.
06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 875248.
2/5 71C ✓