

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004667/BGA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900251503

Claimant Vehicle No : SJQ8957D **Insured Vehicle No :** SKV9995Z

Date of Loss: 31/03/2020 Nature of Claim: TP Claim No: 2677772047SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ8957D		
Make & Model:	HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)	Engine No:	G4FC9U654836
Reg. Date:	29/05/2009 (Man. Year: 2009)	Chassis No:	KMH DU41BR9U761233
Colour:	Red	Odometer:	376946 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,977.79	1,964.23	5,013.56	71.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,920.00	1,790.00	48.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,687.79	3,884.23	6,803.56	63.66
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	10,687.79	3,100.00	7,587.79	70.99
+ GST 7.00/7.00% (\$\$)	748.15	217.00	531.15	71.00
Nett Amount (\$\$)	11,435.94	3,317.00	8,118.94	70.99
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,684.45		

INSPECTION

Date of Assignment: 01/04/2020

Date Inspected: 01/04/2020 Inspected At:

160 SIN MING DRIVE #01-14
Repairer: Team Autopro Pte Ltd (Sin Ming)

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	524.30 FL	*435.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	Necessary	82.40 FL	*65.00 FL
3	1		*FRONT DOOR LH	Repair	1,238.80 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE LH	Not Damaged	345.20 FL	*- FL
5	1		*FRONT DOOR BLACK TAPE LH	Necessary	108.50 FL	*60.00 FL
6	1		*FRONT DOOR WEATHERSTRIP LH	Not Damaged	245.30 FL	*- FL
7	1		*FRONT SIDE MIRROR ASSY LH	Repair	652.80 FL	*- FL
8	1		*FRONT FENDER LH	Dented	489.50 FL	*398.70 FL
9	1		*FRONT FENDER INNER COWLING LH	Not Damaged	259.60 FL	*- FL
10	1		*FRONT FENDER EMBLEM TVV	Necessary	89.50 FL	*16.00 FL
11	1		*FRONT SHOCK ABSORBER	Not Damaged	458.60 FL	*- FL
12	1		*FRONT LOWER ARM	Bent	492.10 FL	*282.00 FL
13	1		*FRONT KNUCKLE ARM	Dented	482.30 FL	*363.00 FL
14	1		*FRONT KNUCKLE ARM BEARING	Jammed	384.20 FL	*285.00 FL
15	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
16	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
17	1		*ALOY RIM (LOCAL REPAIR)	Scratched	850.00 FS	*200.00 FS
18	1		*TYRE	Not Damaged	380.00 FS	*- FS
19	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,563.10	2,154.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	585.31	190.47
Total Parts (\$\$)	6,977.79	1,964.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT & TYRE	New	80.00	50.00
2	WHEEL BALANCING	New	80.00	30.00
3	R&R FRONT DOOR COMPONENT	New	300.00	0.00
4	R&R UPHOLSTERY	New	100.00	0.00
5	CHECK WIRING	New	150.00	30.00
6	R&R UNDERCARRIAGE	New	300.00	150.00
7	WHEEL ALIGNMENT	New	150.00	60.00
8	PANEL BEAT	New	1,200.00	800.00
9	RUST PROOFING	New	150.00	0.00
10	SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,710.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >