

NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0013/03/20
M/S : **THIRD PARTY CLAIM**
GOH WEN CHIANG
BLK 871B EDGEFIELD PLAINS
#05-525
SINGAPORE 822871

Page : 1/1
Date : 30/03/2020

*not Asst
due
r/s \$ 800 /
2 days.
the job is the rep--*

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLP5447K - TOYOTA SIENTA
INSURED : GOH WEN CHIANG
DATE OF ACCIDENT : 29/03/20
POLICY NO : MP307382

ENGINE# :
CHASSIS# : NHP1707072137

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 front fog lamp outer protector <i>grand</i>	10	112.50	112.50	112.50 ✓
2 front fog lamp <i>11</i>	10	355.00	355.00	355.00 ✓
3 front bumper <i>10 lent 804.42</i>	10	950.40	950.40	950.40 ✓
4 front buimper side retainer RH <i>11</i>	10	48.10	48.10	48.10 X
				1,466.00
				-366.50
				\$1,099.50
Less 25%				
Total Material				
Labour & Misc				
1 Remove & install f/bumper, f/bumper fog lamp, f/headlamp, knock headlamp support panel and restraighthen body.				300.00 <i>150</i>
2 Spray painting.				400.00 <i>200</i>
3 Check wiring system.				25.00 ✓
				725.00
				0.00
				\$725.00
Total Labour				\$1,824.50
Nett Total Before Gst				

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: