

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH708B

MAKE & MODEL : NISSAN CABSTAR

CHASSIS NO : JN1SC2F24Z0860979

DATE : 20 MARCH 2020

CLAIM TYPE : 3RD PARTY CLAIM

D.O.A : 22/10/2019

TO : GREAT AMERICAN

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR TAILGATE X(R)		\$ 1,459.60	\$ 1,459.60
2	1	REAR TAILGATE LOCK L/H Xun		\$ 218.90	\$ 218.90
3	1	REAR TAILGATE LOCK R/H Xun		\$ 218.90	\$ 218.90
4	1	TAILLAMP L/H Br		\$ 266.50	\$ 266.50
5	1	REAR SPARE TYRE BRACKET 1st		\$ 380.00	\$ 380.00
6	1	REAR SPARE TYRE BRACKET LOCK 1st		\$ 291.20	\$ 291.20
7	1	REAR NUMBER PLATE LAMP Xun		\$ 80.20	\$ 80.20
8	1	REAR TAILGATE NISSAN STICKER nec		\$ 80.10	\$ 80.10
				\$ 2,995.40	\$ 2,995.40


\$589.59

TOTAL PRICE	\$ 2,995.40
LESS 10%	\$ 299.54
SUB TOTAL PRICE	\$ 2,695.86

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	Rear Reverse Sensor Set 1st		\$ 250.00	\$ 250.00
2	1	Rear Tail Lamp Clips Set nec		\$ 50.00	\$ 50.00
3	1	Pax sticker nec		\$ 10.00	\$ 10.00
4	1	Rear Speed Limit Stickers nec		\$ 10.00	\$ 10.00
5	1	Company Emblem nec		\$ 70.00	\$ 70.00
6	1	Car Plate W Holder Xun		\$ 45.00	\$ 45.00

\$315

TOTAL S/NETT	\$ 435.00	\$ 435.00
--------------	-----------	-----------



LKK Auto Consultants hence notify the Repairer of the follow up:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be replaced
- Final cost is subject to final assessment

Acknowledged by Repairer:
Signature: _____
Date: _____

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH708B
MAKE & MODEL : NISSAN CABSTAR
CHASSIS NO : JN1SC2F24Z0860979

DATE : 20 MARCH 2020
CLAIM TYPE : 3RD PARTY CLAIM
D.O.A : 22/10/2019

TO : AGENT AMERICAN

Labour Charges

- 1 To disimantle and Re-fix damaged Rear portions; affected damaged portion.
- 2 To apply anti rust coat and Tuff Kote affected areas
- 3 To check lighting & wiring
- 4 To Spray painting for Front and Rear Portions affected parts
- 5 To apply waterproofing sealer on end panels

\$	800.00	\$300
\$	70.00	\$30
\$	80.00	\$50
\$	600.00	\$300
\$	80.00	xm

TOTAL LABOUR

Total Cost of Repairs

(Total parts + Total S/Nett + Total Labour Cost)

\$ 1,630.00
\$ 4,760.86

\$680

PR
\$1584.59
3 repairs

PREPARE BY



34/04/2020 Ram (Lkr)
Ramaswami Lkratoram
88622778
AA Repair day 5
3 repair day 5

PAGE 2 OF 2