

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte I
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 708B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,459.60	-
1	REAR TAILGATE LOCK L/H	NOT NECESSARY	218.90	-
1	REAR TAILGATE LOCK R/H	NOT NECESSARY	218.90	-
1	TAILLAMP L/H	BROKEN	266.50	179.00
1	REAR SPARE TYRE BRACKET	BENT	380.00	158.00
1	REAR SPARE TYRE BRACKET LOCK	BENT	291.20	238.00
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	80.20	-
1	REAR TAILGATE NISSAN STICKER	NECESSARY	80.10	80.10
	LESS 10% DISCOUNT		-299.54	-65.51
			2,695.86	589.59
	SPECIAL NETT ITEMS			
1	SET REAR REVERSE SENSOR (SN)	SHORT CIRCUIT	250.00	200.00
1	SET REAR TAIL LAMP CLIPS (SN)	NECESSARY	50.00	25.00
1	PAX STICKER (SN)	NECESSARY	10.00	10.00
1	REAR SPEED LIMIT STICKER (SN)	NECESSARY	10.00	10.00
1	COMPANY EMBLEM (SN)	NECESSARY	70.00	70.00
1	CAR PLATE W HOLDER (SN)	NOT NECESSARY	45.00	1
			435.00	315.00
	<u>LABOUR</u>			
	TO DISMANTLE AND RE-FIX DAMAGED REAR PORTIONS; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		800.00	300.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS.		70.00	30.00
	TO CHECK LIGHTING & WIRING.		80.00	50.00
	TO SPRAY PAINTING FOR FRONT AND REAR PORTIONS AFFECTED PARTS.		600.00	300.00
	TO APPLY WATERPROOFING SEALER ON END PANELS.	NOT NECESSARY	80.00	
			1,630.00	680.00
	GRAND TOTAL		4,760.86	1,584.59

Report Ref No. CS/GAI20004682/Qyd3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			1,584.59	
-----------------------------	--	--	----------	--

Report Ref No. CS/GAI20004682/Qyd3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

N/S

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.