

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 1690 R

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00 ✓	\$360-00
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.		\$ 2,800.00	1000 \$1000-00
3	To respray front bumper and bonnet.		\$ 2,000.00	1100 \$1100-00
4	To carry out diagnostic check.	S/N	\$ 192.00 ✓	\$192-00
TOTAL LABOUR CHARGES		:	<u>\$ 5,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 1690 R

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,894.00	Ry
2	FRONT BUMPER FIXING PARTS	\$ 176.00	X
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 72.00	X
4	FRONT BUMPER GRILLE - CENTRE	\$ 151.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 505.00	X
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 560.00	X
7	FRONT BUMPER COVER TRIM - LH / RH	2 \$ 306.00	X
8	RADIATOR GRILLE	\$ 1,338.00	Cy - \$1070-9
9	RADIATOR GRILLE CLOSING ELEMENT	\$ 180.00	?
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 354.00	X
11	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 681.00	?
12	FRONT BUMPER FOAM FILLER PIECE	\$ 178.00	?
13	FOAM FILLER PIECE COVER	\$ 115.00	?
14	AIRCON STICKER	NEC \$ 7.00	4 ne - \$5-36
15	CAUTION SIGN STICKER	NEC \$ 13.00	? ne - \$10-24
16	SIGNAL HORN - LH HIGH TONE	\$ 188.00	X n n
17	SIGNAL HORN - RH LOW TONE	\$ 188.00	X n n
18	BONNET aluminium	\$ 2,988.00	bt - \$2390-40
19	BONNET ATTACHMENT PARTS	\$ 155.00	net - 17
20	BONNET EDGE PROTECTION	\$ 26.00	ne - \$20-80
SUB TOTAL SPARE PARTS CHARGES		: \$ 10,075.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 1690 R

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	BONNET CATCH HOOK	\$ 84.00	X
22	BONNET STRIKER - LH / RH	2 \$ 208.00	X
23	BONNET LID LOCK	2 \$ 403.00	X
24	BONNET BOWDEN CABLE - CENTRE	\$ 54.00	X
25	LED HEADLIGHT - LH / RH	2 \$ 10,386.00	X
26	LIFT CYLINDER - LH / RH	2 \$ 268.00	X
27	LIFT CYLINDER HOSE	\$ 64.00	X
28	RADIATOR AIR GUIDE - LH / RH	2 \$ 46.00	X
29	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	X
30	FRONT NO PLATE	S/N \$ 60.00	OK \$60.00
31	SUNDRIES	\$ 300.00	2Xnn
TOTAL SPARE PARTS CHARGES		: \$ 21,960.00	
TOTAL LABOUR CHARGES		: \$ 5,352.00	
GRAND TOTAL		: \$ 27,312.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.