

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34167

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0337/2020/NS
Date : 27-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Foo Sin Kwang (Fu Xingguang)
Address : Blk 1D Cantonment Road
#15-37
Singapore 085401
Telephone : HP +65 90229990
Type of Claim : Own Damage Claims
Policy No. : 1800126812
Vehicle No : **SMF 1690 R**
Model Code : Audi A3 Sedan 1.4 TFSI CO
Model / Year : Oct-18
Engine No : CZE 836377
Chassis No : WAUZZZ8V4K1002295
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Mar-20
Place of Accident : Tiong Bahru Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 1690 R

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00 ✓	\$360-00
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.		\$ 2,800.00	1000 \$1000-00
3	To respray front bumper and bonnet.		\$ 2,000.00	1100 \$1100-00
4	To carry out diagnostic check.	S/N	\$ 192.00 ✓	\$192-00
TOTAL LABOUR CHARGES		:	<u>\$ 5,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 1690 R

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,894.00	Ry
2	FRONT BUMPER FIXING PARTS	\$ 176.00	X
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 72.00	X
4	FRONT BUMPER GRILLE - CENTRE	\$ 151.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 505.00	X
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 560.00	X
7	FRONT BUMPER COVER TRIM - LH / RH	2 \$ 306.00	X
8	RADIATOR GRILLE	\$ 1,338.00	Ch - \$1070-4
9	RADIATOR GRILLE CLOSING ELEMENT	\$ 180.00	?
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 354.00	X
11	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 681.00	?
12	FRONT BUMPER FOAM FILLER PIECE	\$ 178.00	?
13	FOAM FILLER PIECE COVER	\$ 115.00	?
14	AIRCON STICKER	NEC \$ 7.00	ne - \$5-36
15	CAUTION SIGN STICKER	NEC \$ 13.00	ne - \$10-24
16	SIGNAL HORN - LH HIGH TONE	\$ 188.00	X nn
17	SIGNAL HORN - RH LOW TONE	\$ 188.00	X nn
18	BONNET aluminium	\$ 2,988.00	bt - \$2390-40
19	BONNET ATTACHMENT PARTS	\$ 155.00	ne
20	BONNET EDGE PROTECTION	\$ 26.00	ne - \$20-80
SUB TOTAL SPARE PARTS CHARGES		: \$ 10,075.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 1690 R

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	BONNET CATCH HOOK	\$ 84.00	X
22	BONNET STRIKER - LH / RH	2 \$ 208.00	X
23	BONNET LID LOCK	2 \$ 403.00	X
24	BONNET BOWDEN CABLE - CENTRE	\$ 54.00	X
25	LED HEADLIGHT - LH / RH	2 \$ 10,386.00	X
26	LIFT CYLINDER - LH / RH	2 \$ 268.00	X
27	LIFT CYLINDER HOSE	\$ 64.00	X
28	RADIATOR AIR GUIDE - LH / RH	2 \$ 46.00	X
29	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	X
30	FRONT NO PLATE	S/N \$ 60.00	bl - \$60.00
31	SUNDRIES	\$ 300.00	? X nn
TOTAL SPARE PARTS CHARGES		:	\$ 21,960.00
TOTAL LABOUR CHARGES		:	\$ 5,352.00
GRAND TOTAL		:	\$ 27,312.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Tanfai 97445749
Surveyed Date : Not Authorised
Authorised Date : Ex: to be advise
Excess Cost : Resurvey before paint
Liability : 25 days
Remarks :
sur @ 11/11/20
30/4/20

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant