LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building 78 Shenton Way #08-16 Singapore 079120 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 31 Mar 2020

Preliminary Advice

Vehicle No : SKL8043E Accident Date : 27/03/2020 Make : AUDI A3 SB Policy No. : 2100359226-06 Assignment Date : 31/03/2020 **Excess** : S\$ 600.00 Date of Inspection : 30/03/2020 Est. Duration of Repair : 4 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,105.00
Revised Amount	:S\$	7,379.00
Check Items (Estimated)	:S\$	1,209.00
Total	:S\$	8,588.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 45,000.00

 COE / PARF Rebate
 :S\$ 38,107.00

Salvage Value :S\$

Margin for Repair :S\$ 6,893.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Margin for repair is \$ 6,893.00. Repairer able to undertake the repair cost not exceeding \$ 6,500.00.