

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883  
Email: SM\_AUTOMOTIVE@HOTMAIL.COM  
Tel: (65) 6747 9241 Fax: (65) 6741 7276  
RCB No.: 53231488C

27/03/2020

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

Accident date: 27/3/2020

Supplimentary repair cost for vehicle no: SJN4210S TOYOTA ALTIS A 1.6 ' 09

CHASSIS: MR053ZEE106140142

S/n	Qty	Items	U/price	Amount
1	2	Front Horn	\$45.00	\$90.00
2	1	Front Wire Harness		\$1,080.00
3	1	Front Air Intake Resonator		\$105.00
4	1	Front Gearbox Mounting		\$105.00
5	3	Front Engine Mounting	\$150.00	\$450.00
6	1	Front Engine Mounting Bracket		\$95.00
7	1	Front Engine Starter		\$680.00
8	1	Front Center Cross Member		\$1,200.00
9	1	Front ABS Pump		\$2,920.00
10	1	Front ABS Pipe Assy		\$790.00
11	1	Front Air-Con Valve		\$65.00
12	1	Front Air-Con Top-Up Pipe		\$120.00
13	1	Front Compressor		\$450.00
14	1	Front Alternator		\$700.00
15	1	Front Wheel Housing		\$1,080.00
16	1	Front Wiper Garnish		\$145.00
17	1	Front L/H Chassis		\$1,100.00
18	1	Rear Engine Mounting Bracket		\$125.00

Total:- \$11,300.00

Cost + 10% :- \$12,430.00