

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

UP Claim
CTPI

27-03-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 27/3/2020

Estimated repair cost for vehicle no: SJN4210S TOYOTA ALTIS A 1.6 ' 09

CHASSIS: MR053ZEE106140142

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Front Windscreen <i>cauled</i>		\$571.50	✓
2	1	Front Windscreen Moulding <i>3/4</i>		\$88.90	✓
3	1	Front Windscreen Seal		\$35.00	✓
4	1	Front Bonnet <i>Distorted</i>		\$571.50	✓
5	2	Front Bonnet Hinge <i>Best</i>	\$35.00	\$70.00	✓
6	1	Front Bonnet Insulator <i>Caupled</i>		\$190.50	✓
7	8	Front Bonnet Insulator Clips <i>nu</i>	\$1.50	\$12.00	✓
8	1	Front Bonnet Inner Rubber <i>at</i>		\$35.00	✓
9	1	Front Bonnet Lock <i>Jammed</i>		\$58.00	✓
10	1	Front Bonnet Lock Panel <i>Best</i>		\$58.00	✓
11	2	Front Head Lamp <i>RA Smashed, LH ?</i>	\$175.00	\$350.00	175
12	2	Front Head Lamp Lower Bracket <i>?</i>	\$35.00	\$70.00	?
13	1	Front Bumper <i>Distorted</i>		\$250.00	✓
14	2	Front Bumper Side Retainer <i>nu</i>	\$35.00	\$70.00	✓
15	10	Front Bumper Clips <i>nu</i>	\$2.00	\$20.00	✓
16	1	Front Bumper Number Plate <i>Best</i>		\$50.00	✓
17	2	Front Bumper Fog Lamp <i>3/4</i>	\$75.00	\$150.00	+
18	2	Front Bumper Fog Lamp Cover <i>3/4</i>	\$65.00	\$130.00	+
19	1	Front Bumper Lower Grille <i>Del</i>		\$85.00	✓
20	1	Front Bumper Under Cover <i>ton</i>		\$105.00	✓
21	1	Front Bumper Reinforcement <i>Best</i>		\$175.00	✓
22	1	Front Bumper Centre Top Rubber <i>at</i>		\$35.00	✓
23	6	Front Bumper Centre Top Rubber Clips <i>nu</i>	\$2.00	\$12.00	✓
24	1	Front Grille <i>cauled</i>		\$135.00	✓
25	1	Front Grille Inner <i>?</i>		\$175.00	?
26	1	Front Grille Emblem Logo <i>nu</i>		\$35.00	✓
27	6	Front Grille Clip <i>nu</i>	\$2.00	\$12.00	✓
28	2	Front Fender <i>RA Distorted</i>	\$175.00	\$350.00	175

29	2	Front Fender Cowling	RA Del'd	\$90.00	\$180.00 70
30	16	Front Fender Cowling Clips	new	\$2.00	\$32.00 16.
31	2	Front Fender Inner Cover	new	\$105.00	\$210.00 +
33	1	Front Support Panel	Disto Ld.		\$330.00 ✓
34	2	Front Support Panel Air Duct	?	\$95.00	\$190.00 ?
35	1	Front Battery	?		\$150.00 ?
36	1	Front Battery Bracket	Bent		\$58.00 ✓
37	1	Front Battery Tray	?		\$58.00 ?
38	2	Front Chassis Bracket	new	\$75.00	\$150.00 +
39	1	Front Air-con Condenser	Disto Ld.		\$205.00 ✓
40	1	Front Air-con Section Pipe	Bent		\$250.00 ✓
41	1	Front Air-con Discharge Pipe	Bent		\$250.00 ✓
42	1	Front Air-con Fan Motor Assy	smashed. new		\$380.00 +.
43	1	Front Wiper Tank	Del'd		\$105.00 ✓
44	1	Front Wiper Tank Motor	new		\$105.00 +.
45	1	Front Radiator	Disto Ld.		\$450.00 ✓
46	1	Front Radiator Fan Motor Assy	Disto Ld.		\$380.00 ✓
47	1	Front Radiator Tank	Del'd.		\$105.00 ✓
48	1	Front Radiator Top Hose	finished		\$35.00 ✓
49	1	Front Radiator Inner Hose	new		\$35.00 ✓
50	2	Front Radiator Bracket	Bent	\$35.00	\$70.00 ✓
51	2	Front Radiator Top Bracket & Rubber Assy	new	\$35.00	\$70.00 ✓
52	1	Front Exhaust Manifold (Black Color)	?		\$330.00 ?

Subtotal:- \$8,027.40

Cost + 10% :- \$8,830.14

Labour charges

To remove & refit front air-con condenser, radiator, fan motor
& top-up gas

~~\$280.00~~ 120

To remove & refit front windscreen

\$120.00 ✓

Gum

\$60.00 ✓

To check wiring

~~\$100.00~~ 30

Panel beating

~~\$2,400.00~~ 1400

Spray painting

~~\$1,600.00~~ 1200

Subtotal:- \$4,560.00

Total:- \$13,390.14

Adrian L
t/s 31/03/20

10 Days.

Not Authorised,

Exens : To be advised

2.45pm -> Still checking.
once ready will
email out.