

OD Claim

CTPI

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

27-03-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 27/3/2020

Estimated repair cost for vehicle no: SJN4210S TOYOTA ALTIS A 1.6 ' 09

CHASSIS: MR053ZEE106140142

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Front Windscreen <i>cracked</i>		\$571.50	✓
2	1	Front Windscreen Moulding <i>2pc</i>		\$88.90	✓
3	1	Front Windscreen Seal		\$35.00	✓
4	1	Front Bonnet <i>Distorted</i>		\$571.50	✓
5	2	Front Bonnet Hinge <i>Best</i>	\$35.00	\$70.00	✓
6	1	Front Bonnet Insulator <i>Cracked</i>		\$190.50	✓
7	8	Front Bonnet Insulator Clips <i>new</i>	\$1.50	\$12.00	✓
8	1	Front Bonnet Inner Rubber <i>cut</i>		\$35.00	✓
9	1	Front Bonnet Lock <i>Jammed</i>		\$58.00	✓
10	1	Front Bonnet Lock Panel <i>Best</i>		\$58.00	✓
11	2	Front Head Lamp <i>RH Smashed, LH Cracked</i>	\$175.00	\$350.00 175	✓
12	2	Front Head Lamp Lower Bracket <i>new</i>	\$35.00	\$70.00	✓
13	1	Front Bumper <i>Distorted</i>		\$250.00	✓
14	2	Front Bumper Side Retainer <i>new</i>	\$35.00	\$70.00	✓
15	10	Front Bumper Clips <i>new</i>	\$2.00	\$20.00	✓
16	1	Front Bumper Number Plate <i>Best</i>		\$50.00	✓
17	2	Front Bumper Fog Lamp <i>2pc new</i>	\$75.00	\$150.00	✓
18	2	Front Bumper Fog Lamp Cover	\$65.00	\$130.00	✓
19	1	Front Bumper Lower Grille <i>Del</i>		\$85.00	✓
20	1	Front Bumper Under Cover <i>new</i>		\$105.00	✓
21	1	Front Bumper Reinforcement <i>Best</i>		\$175.00	✓
22	1	Front Bumper Centre Top Rubber <i>cut</i>		\$35.00	✓
23	6	Front Bumper Centre Top Rubber Clips <i>new</i>	\$2.00	\$12.00	✓
24	1	Front Grille <i>cracked</i>		\$135.00	✓
25	1	Front Grille Inner <i>new</i>		\$175.00	✓
26	1	Front Grille Emblem Logo <i>new</i>		\$35.00	✓
27	6	Front Grille Clip <i>new</i>	\$2.00	\$12.00	✓
28	2	Front Fender <i>RH Distorted</i>	\$175.00	\$350.00 175	✓

29	2	Front Fender Cowling	RH Del'd	\$90.00	\$180.00 70
30	16	Front Fender Cowling Clips	new	\$2.00	\$32.00 16
31	2	Front Fender Inner Cover	new	\$105.00	\$210.00 +
33	1	Front Support Panel	Dist'd		\$330.00 ✓
34	2	Front Support Panel Air Duct	RH new	\$95.00	\$190.00 ✗
35	1	Front Battery	Not new		\$150.00 ✗
36	1	Front Battery Bracket	Best		\$58.00 ✓
37	1	Front Battery Tray	new		\$58.00 ✗
38	2	Front Chassis Bracket	new	\$75.00	\$150.00 +
39	1	Front Air-con Condenser	Dist'd		\$205.00 ✓
40	1	Front Air-con Section Pipe	Best		\$250.00 ✓
41	1	Front Air-con Discharge Pipe	Best		\$250.00 ✓
42	1	Front Air-con Fan Motor Assy	smashed. new		\$380.00 +
43	1	Front Wiper Tank	Del'd		\$105.00 ✓
44	1	Front Wiper Tank Motor	new		\$105.00 +
45	1	Front Radiator	Dist'd		\$450.00 ✓
46	1	Front Radiator Fan Motor Assy	Dist'd		\$380.00 ✓
47	1	Front Radiator Tank	Del'd		\$105.00 ✓
48	1	Front Radiator Top Hose	twisted		\$35.00 ✓
49	1	Front Radiator Inner Hose	new		\$35.00 ✓
50	2	Front Radiator Bracket	Best	\$35.00	\$70.00 ✓
51	2	Front Radiator Top Bracket & Rubber Assy	new	\$35.00	\$70.00 ✓
52	1	Front Exhaust Manifold (Black Color)	new		\$330.00 ✓

5578.40

Subtotal:- \$8,027.40

6576.24

Cost + 10% :- \$8,830.14

Labour charges

To remove & refit front air-con condenser, radiator, fan motor
& top-up gas

~~\$280.00~~ 120

To remove & refit front windscreen

\$120.00 ✓

Gum

\$60.00 ✓

To check wiring

2830

~~\$100.00~~ 30

Panel beating

~~\$2,400.00~~ 1400

Spray painting

~~\$1,600.00~~ 120

Subtotal:- \$4,560.00

Total:- \$13,390.14

Supplementary: \$218.50

total 13504.74

Adrian Lj

4/s 10.8K

1/s 31/03/20

10.8K

10 Days.

Not Authorised,

Exens : To be advised

2.45pm - still checking
once ready will
email out

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

27/03/2020

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

Store (1/4/20)

Accident date: 27/3/2020

Supplimentary repair cost for vehicle no: SJN4210S TOYOTA ALTIS A 1.6 ' 09

CHASSIS: MR053ZEE106140142

S/n	Qty	Items	U/price	Amount	
1	1/2	Front Horn / BR	\$45.00	\$90.00	45 ✓
2	1	Front Wire Harness / TAN (\$300 To repair back) Local repair		\$1,080.00	\$300 300
3	1	Front Air Intake Resonator X		\$105.00	X ✓
4	1	Front Gearbox Mounting / BT		\$105.00	✓
5	3	Front Engine Mounting / BT	\$150.00	\$450.00	✓
6	1	Front Engine Mounting Bracket / BT		\$95.00	✓
7	1	Front Engine Starter X		\$680.00	X ✓
8	1	Front Center Cross Member X		\$1,200.00	X 1200
9	1	Front ABS Pump / BR		\$2,920.00	✓ 2920
10	1	Front ABS Pipe Assy / BT		\$790.00	✓ 790
11	1	Front Air-Con Valve / mis		\$65.00	✓
12	1	Front Air-Con Top-Up Pipe / BT		\$120.00	✓
13	1	Front Compressor X Repair back Repair back		\$450.00	X 450
14	1	Front Alternator /		\$700.00	✓ 700
15	1	Front Wheel Housing X Repair Repair		\$1,080.00	X 1080
16	1	Front Wiper Garnish X		\$145.00	X ✓
17	1	Front L/H Chassis X R		\$1,100.00	X ✓
18	1	Rear Engine Mounting Bracket / BT		\$125.00	✓

Total:- \$11,300.00

Cost + 10% :- \$12,430.00

3635
3598.50