

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

27/03/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Store (1/4/20)

Accident date: 27/3/2020

Supplimentary repair cost for vehicle no: SJN4210S TOYOTA ALTIS A 1.6 '09

CHASSIS: MR053ZEE106140142

S/n	Qty	Items	U/price	Amount
1	1	Front Horn / BR	\$45.00	\$90.00
2	1	Front Wire Harness / TN (\$790 To Repair back) Local repair		\$1,080.00
3	1	Front Air Intake Resonator X		\$105.00
4	1	Front Gearbox Mounting / BT		\$105.00
5	3	Front Engine Mounting / BT	\$150.00	\$450.00
6	1	Front Engine Mounting Bracket / BT		\$95.00
7	1	Front Engine Starter X		\$680.00
8	1	Front Center Cross Member X		\$1,200.00
9	1	Front ABS Pump / BR		\$2,920.00
10	1	Front ABS Pipe Assy / BT		\$790.00
11	1	Front Air-Con Valve / mis		\$65.00
12	1	Front Air-Con Top-Up Pipe / BT		\$120.00
13	1	Front Compressor X Repair Repair back		\$450.00
14	1	Front Alternator /		\$700.00
15	1	Front Wheel Housing X Repair Repair		\$1,080.00
16	1	Front Wiper Garnish X		\$145.00
17	1	Front L/H Chassis X R		\$1,100.00
18	1	Rear Engine Mounting Bracket / BT		\$125.00

Total:- \$11,300.00

Cost + 10% :- \$12,430.00