

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

REPAIR LIMIT : \$

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
JACQUELINE
TAY BEE HONG
56 CORONATION ROAD WEST
#05-04
Singapore 269269

Document no.
Document date 31-03-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020007574/ 1
Job order date 30-03-2020
Service Advisor EDMUND, HUI HUANG GOH

License plate	Model code	First registration	VIN	Model	Mileage
SJU4603E	1C13DA	10-12-2009	VWVZZZ9CZ9M559451	New Beetle I2 75/1.6A6F	123,203

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00	299.60
1C0807649M GRU	Cover For Bumper Primed	1	pcs.	1,386.50 de ✓	#1	1,386.50	1,483.56
1C0807305M	Bumper	1	pcs.	454.64 ?	#1	454.64	486.46
	(BUMPER REINFORCEMENT)						
1C0825322A 01C	Air Duct Satin Black → * photo.	1	pcs.	103.66 de ✓	#1	103.66	110.92
	(BUMPER LOWER GRILLE)						
1C0807711L	Support	1	pcs.	346.98 ?	#1	346.98	371.27
	(BUMPER BRACKET LH)						
1C0807712N	Support	1	pcs.	346.98 ?	#1	346.98	371.27
	(BUMPER BRACKET RH)						
1J6943021B	License Plate Light	2	pcs.	32.05 ?	#1	64.10	68.59
1C0941071G	Back-Up Light	1	pcs.	171.56 ana ✓	#1	171.56	183.57
	(LH)						
1C0945702D	Rear Fog Light	1	pcs.	178.19 ?	#1	178.19	190.66
	(RH)						
	REAR NUMBER PLATE	1	pcs.	80.00 bt ✓	#1	80.00	85.60
	LABOUR	4	pcs.	840.00	#1 840	3,360.00	3,595.20
	Spray Painting	3	pcs.	800.00	#1 800	2,400.00	2,568.00
	REVERSE SENSORS * photo.	1	pcs.	400.00	#1 nw ✓	400.00	428.00

Quotation valid till 06-04-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,292.61	7%	703.68	10,052.61	10,756.29
Total	760.00	9,292.61		703.68	10,052.61	10,756.29

Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

-----VISIT OUR WEBSITE: aftersales.volkswagen.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

Signature:

Date:

Tanpin 97495719
wp
3/4/2020 1115

03 days Service Advisor
Resurvey before paint
tanpin lkkauto.com

* To check repair limit
\$7000 limit

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
JACQUELINE
TAY BEE HONG
56 CORONATION ROAD WEST
#05-04
Singapore 269269

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

31-03-2020
5211043795
201009404M
30001
2020007574/ 1
30-03-2020
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SJU4603E	1C13DA	10-12-2009	WVWZZZ9CZ9M559451	New Beetle I2 75/1.6A6F	123,203