

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 30/3/2020

Vehicle: SKQ3337P

Make / Model: MERCEDES BENZ C200

Chassis: WDD2040412A337809

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	LH FORNT DOOR	1	\$ 2,002.00	\$ 2,002.00
2	LH FRONT DOOR MIRROR (Chassis)	1	\$ 1,170.00	\$ 1,170.00
3	LH FRONT DOOR MIRROR COVER	1	\$ 407.00	\$ 407.00
4	LH FRONT DOOR MIRROR SIGNAL LAMP	1	\$ 495.00	\$ 495.00
5	FLH FRONT DOOR MIRROR GLASS	1	\$ 295.00	\$ 295.00
				\$ 4,369.00
			Less 10%	\$ 436.90
			Total	\$ 3,932.10
	S/Nett items:			
				\$ -
	Labour to:			
40	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00
44	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
45	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
46	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
				\$ 1,170.00
			Parts Replacement Amount	\$ 3,932.10
			Total Amount for Labour	\$ 1,170.00
			Total Amount	\$ 5,102.10

© 2070

Survey + Resurvey
31/3/2020

Terim bin
1230 hrs

Lump sum repair
Repair days 4

L/S 2750/2

Trina M
1/4/2020