

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

30/3/2020

Vehicle:

SKQ3337P

Make / Model:

MERCEDES BENZ C200

Chassis:

WDD2040412A337809

2009

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	LH FORNT DOOR	1	\$ 2,002.00	\$R 2,002.00	200 1900
2	LH FRONT DOOR MIRROR (Chass	(5) 1	\$ 1,170.00	\$ 1,170.00	JAN V 901.
3	LH FRONT DOOR MIRROR COVER	1	\$ 407.00	\$ 407.00	CUTV 317
4	LH FRONT DOOR MIRROR SIGNAL LAMP	1	\$ 495.00	\$ND 495.00	NEC V 108
5	FLH FRONT DOOR MIRROR GLASS	1	\$ 295.00	\$ND 295.00	BR V 285
				\$ 4,369.00	011
			Less 10%	\$ 436.90	3.00
			Total	\$ 3,932.10	
	S/Nett items:				-104.1
	200 00000000000000000000000000000000000			\$ -	
	Labour to:				
40	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00	1
44	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00	NNX
45	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$300,500.00	/
46	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$3000500.00	
	(M			\$ 1,170.00	750 00
	Ţ,	Parts Replace	nent Amount	\$ 3,932.10	2
		Total Amount for Labour		\$ 1,170.00	
		Total Amount		\$ 5,102.10	2,457.6
				@ 20%	A91.5

Survey + Resurvey 31/3/2020 Talin Min 1230 lars

> Lump sum repair Repair days 4

45-27-50/2

LKK Anto Copenhante sanca notify

- · To resummy but
- * To display at many or provide a second position
- · Pacus multiple
- a Thursday
- No Disk
- Supplementary
 To subject to the second sec

Admontection by Regard Signature: TGIM Mi 1/4/2000