

Lian Her Motors

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

H.L. Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Not Withheld
L1 Rep 87
Resurvey After Paint
2 days

Vehicle No : SLU 8113 C
Make : Toyota C-HR
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front grille <i>photo</i>	CRACKED	\$434.80	7
1 pc	Front grille emblem <i>photo</i>	DENTED	\$1,654.60	?
1 pc	Front o/s headlamp assy <i>photo</i>	MTG CRACKED	\$1,804.30	?
1 pc	Front bumper	CM	\$1,236.70	✓
1 pc	Front bumper upper reinforcement X	REPAIR	\$461.60	7X
1 pc	Front bumper upper reinforcement sponge <i>photo</i>	CRACKED	\$95.20	?
2 pcs	Front bumper upper reinforcement bracket X	\$354.10	\$708.20	XX
1 pc	Front bumper lower reinforcement X		\$273.10	XX
1 pc	Front bumper lower reinforcement sponge <i>photo</i>		\$75.80	X
1 pc	Front bumper lower bumper	MTG	\$499.30	✓
1 pc	Front bumper lower grille <i>photo</i>	CRACKED	\$154.70	?
1 pc	Front no plate holder		\$122.80	X
1 pc	Front o/s bumper side retainer		\$155.20	X
			\$7,676.30	
Less 25 %			\$1,919.08	
			\$5,757.22	

S Nett

20 pcs	Front clip	\$2.00	\$40.00	✓
1 pc	Front no plate		\$35.00	X

Labour Charges

Remove/renew the above parts including knocking, welding etc.	\$500.00	300
To putty & spray paint on accident affected portion.	\$500.00	220
Check and reconnect wiring.	\$30.00	15
Diagnostic check on front collision sensor and reset to factory specification	NOT NECESSARY	\$200.00
Total		\$7,062.22

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: