

Fw: SLU8113C

Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>

Fri 5/15/2020 3:15 PM

To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>

 6 attachments (842 KB)

CCF_000231.pdf; IMG_0498.jpg; IMG_0499.jpg; IMG_0505.jpg; IMG_0506.jpg; IMG_0509.jpg;

L/Sump \$3650.00.

Front grille cracked

Emblem dented

Headlamp mtg cracked

Reinforcement repair

Sponge cracked

Lower grille cracked

Diagnostic check not necessary

From: Anthony Cheong <cheonganthony@yahoo.com.sg>

Sent: Wednesday, 8 April 2020 12:28 PM

To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>

Subject: Fw: SLU8113C

Hi Kenneth,

Attached photos and markings for your necessary action.

Thanks
Anthony