Lian Her Motors

Mailing address: Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225

H/p 91082728

Fax: 64816131

H.L.Car Rental Pte Ltd Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541

Make

: Toyota C-HR

Year

: 2017

Vehicle No: SLU 8113 C

Not Nothonial
LIRA 87
Resury After Paint
2 days

Qty	Description	Unit Price	Amount
Estimate (Cost Of Repair		
Louinato	T I		\$434.80 7
1 pc	Front grille photo		\$1,654.60 ?
1 pc	Front grille emblem		\$1,804.30
1 pc	Front o/s headlamp assy	cm \$1,236.70 L	
1 pc	Front bumper		
1 pc	Front bumper upper reinforcement X		\$461.60 7
1 pc	Front bumper upper reinforcement sponge Front bumper upper reinforcement bracket Front bumper lower reinforcement Front bumper lower reinforcement sponge		\$95.20
2 pcs	Front bumper upper reinforcement bracket K	\$354.10	N \$708.20 X
1 pc	Front-bumper-lower-reinforcement-		1 \$273.10 X
1 pc	Front bumper lower reinforcement sponge	nul	\$75.80 X
1 pc	Front bumper lower bumper	11.01	4.00.00
1 pc	Front bumper lower grille Phelo		Sh \$154.70 5
1 pc	Front no plate holder		5122.80 ×
1 pc	Front o/s bumper side retainer		<u> \$155.20 ₹</u>
			\$7,676.30
		Less 25 %	
			\$5,757.22
S Nett			
			10 01000 -
20 pcs	Front clip	\$2.00	\$40.00
1 pc	Front no plate		\$35.00 X
Labour C	harges		
			\$500.00 3
Remove/	renew the above parts including knocking, welding etc.		\$500.00
To putty 8	& spray paint on accident affected portion.		\$500.00 2
Check an	nd reconnect wiring.		\$30.00 /
Diagnost	ic check on front collision sensor and reset to laston consultants hence notify		\$200.00
	the Repairer of the following:	Total	\$7,062.22
	To resurvey before/after spray painting		
	To display damaged part(s) during resurve	v I	
	 Parts prices are subject to confirmation 		
	 Third party survey is on a "Without Prejudi 	ce" basis	
	 No illegal modification(s) is allowed 		

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date: