

LEE APPRAISAL SERVICES

Business Reg. No.: S3387981K

Email: dylanlee.as@gmail.com

220A Sumang Lane #06-75 (S)821220

Tel: 9101 7844

Fax: 6996 6442

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/1907/FBHH7373L/VC

VEHICLE APPRAISAL REPORT

Mr Phua Poh Chin Report Date : 10 Oct 2019

C/O Goh JP & Wong LLC

133 New Bridge Road #16-09

Chinatown Point

Singapore 059413

REFERENCE

Your Reference No : GTW.ACC.7072.19

Date of Appraisal : Third Party

Date of Accident : 30 Jun 2019

Date of Re-inspection 1 : N.A.

Date of Re-inspection 2 : 08 Oct 2019

PARTICULARS OF VEHICLE

Registration No : FBH7373L
 Make : Harley Davidson
 Model : FLTRXSE2 CVO Road
 Color : Gold / Emerald
 Engine No. : TC8D958615
 Chassis No. : SHD1TC8C7DB958615
 First Reg Date : 16 May 2013
 COE Expiry : 15 May 2023
 Odometer : 31960

CONDITIONS OF VEHICLE (STATIC CHECK AT TIME OF INSPECTION ONLY)

Front Brake : Serviceable
 Rear Brake : Serviceable
 Steering : Serviceable
 Modification : Limited Edition

TYRE / CONDITION

Location	Make & Size	Thread
Front	Mezeler 130/60 B23	5 mm
Rear	Michelin 200/55 R17	6 mm

DAMAGE PROFILE

The vehicle sustained damages on rear portion.

Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

This vehicle is a one & only unique limited edition model locally with market value of about \$70K+
 Repair cost to the vehicle is assessed as \$4,150.00 on lump sum basis
 Estimated period required for repairs: (3) days
 Survey conducted at: Vicious Cycles Parts & Service LLP
 Enclosed (16) photographs depicting damages to the vehicle
 The survey was conducted on a *WITHOUT PREJUDICE* basis.

LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220
 Tel: 9101 7844 Fax: 6996 6442
 Business Reg. No.: 53387981K Email: dylanlee.as@gmail.com



Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/1907/FBH7373L/VC

ASSESSMENT FOR REPAIR : FBH7373L

Qty	Description	Condition	Estimate	Repaire's	Our
1 pc	Saddle bag mounting front support RH	Bent	76.00	76.00	76.00 X R
1 pc	Saddle bag support RH	Bent	484.00	484.00	484.00 X R
1 pc	Rear fender to saddle bag support	Bent	118.00	118.00	118.00 X R
1 pc	Rear fender	Distorted	2,973.00	2,973.00	2,973.00 X SVL
1 pc	Rear fender fascia	Deformed	1,473.00	1,473.00	1,473.00 X SVL
2 pcs	Fascia stiffener plate @52.00	Distorted	104.00	104.00	104.00 X SVL
1 pc	Muffler mounting bracket RH	Bent	37.00	37.00	37.00 X SVL
		Less 10%	5,265.00	5,265.00	5,265.00
			526.50	526.50	526.50
			4,738.50	4,738.50	4,738.50

BT ✓

Labour Charges 500.00
 Workmanship to renew & repair damaged parts & areas 450.00 200

Total Parts & Labours Concluded 5,238.50

5,188.50

Lump Sum Repair Adjustment 4,150.00

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment above.

Yours faithfully,
 LEE APPRAISAL SERVICES



Lee Kah Pang
 Dip Mech Engr, BCompSc