



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 7373L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SADDLE BAG MOUNTING FRONT SUPPORT RH	TO REPAIR SEE LABOUR	76.00	-
1	SADDLE BAG SUPPORT RH	BENT	484.00	484.00
1	REAR FENDER TO SADDLE BAG SUPPORT	TO REPAIR SEE LABOUR	118.00	-
1	REAR FENDER	SERVICEABLE	2,973.00	-
1	REAR FENDER FASCIA	SERVICEABLE	1,473.00	-
2	FASCIA STIFFENER PLATE @ \$52.00	SERVICEABLE	104.00	-
1	MUFFLER MOUNTING BRACKET RH	SERVICEABLE	37.00	-
	LESS 10% DISCOUNT		-526.50	-48.40
			4,738.50	435.60
	<b><u>LABOUR</u></b>			
	WORKSHIP TO RENEW & REPAIR DAMAGED PARTS & AREAS. INCLUSIVE OF THE REPAIR OF SADDLE BAG MOUNTING FRONT SUPPORT RH AND REAR FENDER TO SADDLE BAG SUPPORT.		500.00	200.00
			500.00	200.00
	<b>GRAND TOTAL</b>		<b>5,238.50</b>	<b>635.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>500.00</b>

Report Ref No. CS3/AIG19011969/Ntf3s2-1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.