

**ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Your Ref : SJQ 504 E

Our Ref : CIV1303236 / SLK 2376 C

Date : 06.05.2020

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG Building

78 Shenton Way

#07-16 Singapore 079120

RE : ACCIDENT INVOLVING **SLK 2376 C & SJW 9285 X**
ACCIDENT DATE **27.10.2019**
ACCIDENT ALONG **BALESTIER ROAD**

We are the workshop for the owner of motor vehicle no : SLK 2376 C which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured SJW 9285 X we are submitting these claims for your consideration.

1	Cost of repair	S \$	1,556.43
2	Loss of rental <u>2</u> days @ <u>\$ 83</u> / day	S \$	176.00
<div style="border: 1px solid black; padding: 5px;"><p>DOA : 27.10.2019 PRI Request : 30.03.2020 @ 16:55 Survey Date : 01.04.2020 @ 10:30 to arrange PRI Recommend : 2 days Weekend : Total : 2 days</p></div>			
5	LTA Fee	S \$	7.45
		S \$	1,739.88

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim

Claims Executive

Email : carmen@esteemperf.com.sg



ESTEEM PERFORMANCE PTE LTD

int:1

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co, Reg No. : 200005485N GST Reg No. : 20-0005485-N

M/S : AIG ASIA PACIFIC INSURANCE PTE.LTD
AIG BUILDING
78 SHENTON WAY
#07-16 SINGAPORE 079120

ATTN: Motor Claim Department

Your Ref No: SJQ504E
Claim Type: Third Party
Accident Date: 27/10/2019
TP Veh Reg No: SJQ504E

Claim No: CER1302467
Final No: CIV1303236
Date: 04 May 2020
Policy No: A29114756MKF
Veh Reg No: SLK2376C
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU103540633
Engine No: 2ZRR980616
Reg. Date: 10/01/2017

Tax Invoice to Vehicle No :SLK2376C

Description	Quantity	List Price	Amount
		S\$	S\$
Others			
1 COST OF REPAIR	1 PCS	1,454.61	
		1,454.61	1,454.61
Total			S\$ 1,454.61
Add GST @ 7%			101.82
Total Amount Payable			S\$ 1,556.43

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED FIFTY SIX AND CENTS FORTY THREE ONLY

The above vehicle was surveyed by KENNETH on 01/04/2020

For Esteem Performance Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

PRIVATE CONFIDENTIAL

SCHEDULE TO VEHICLE RENTAL AGREEMENT

Date:	20 September 2019	Vehicle Rental Agreement No.	SL-RA-131-2019
RENTER'S DETAILS			
Primary Driver		Additional Driver (If Any)	
Name (As per NRIC / Passport)	Chung Yee Siang	Name (As per NRIC / Passport)	
Address (As per NRIC)	Apt Blk 156 Ang Mo Kio Avenue 4 #06-702 Singapore 560156	Address (As per NRIC)	
Date of Birth	21 March 1983	Date of Birth	
NRIC / Passport No.	S8308712I	NRIC / Passport No.	
Driving License No.	S8308712I	Driving License No.	
Telephone No.	-	Telephone No.	
Mobile Phone No.	8645 5495	Mobile Phone No.	
Email Address	chungveesiang@gmail.com	Email Address	
RENTED VEHICLE'S DETAILS			
Registration Plate No.	SLK2376C	Chassis No.	JTDKB3FU103540633
Make & Model	Toyota Prius Hybrid 1.8 CVT	Engine No.	2ZRR980616
Exterior Paint Colour	Silver	Interior Colour	Black
RENTAL PERIOD			
Rental Tenure (Months)	6		
Rental Start Date	16 September 2019	Rental End Date	22 March 2020
RENTAL CHARGES* & DEPOSIT			
Rental Charges (GST inclusive if any)	Rental per day @ \$83.00 Rental Per week @ \$581.00	Security Deposit (GST not applicable if any)	\$500.00
Collision Damage Waiver (CDW) (GST inclusive if any)	Rate per day @ \$5.00 Rate Per week @ \$35.00		
Rental Tenure (Days)	188	Total Charges	\$16,544.00
INSURANCE MATTERS (ACCIDENT / THEFT)			
Liability Assessment / Nature of Incident	Non-Refundable Excess Payable by Renter (Including GST) Renter or additional driver must be ≥ 21 & < 70 years of age & > 1 year of driving experience	Rental Charge / Replacement Vehicle	
3rd Party's Fault	\$0.00	Rental Charges waived or replacement vehicle provided (subject to availability but not necessarily to be of the same age, make & model)	
3rd Party's Claims	\$1,070.00	No waiver of Rental Charges, replacement vehicle maybe provided at the discretion of the Lessor but subject to additional Rental Charges	
Own Damage (Including Act of God incidents & accidents in Malaysia)	\$1,070.00	No waiver of Rental Charges, replacement vehicle maybe provided at the discretion of the Lessor but subject to additional Rental Charges	
Stolen Vehicle	\$1,070.00	Rental Charges waived or replacement vehicle provided (subject to availability but not necessarily to be of the same age, make & model)	
Windscreen Damage	\$107.00	No waiver of Rental Charges, replacement vehicle maybe provided at the discretion of the Lessor but subject to additional Rental Charges	
MODE OF PAYMENT			
Grab Cash / Credit Wallet		Cash	
Credit Card		Debit Bank Account (GIRO)	
Type		Bank Name	DBS Current
Card No.		Account No.	003-945163-6

PRIVATE CONFIDENTIAL

Date:	20 September 2019	Vehicle Rental Agreement No.	SL-RA-131-2019
--------------	--------------------------	-------------------------------------	-----------------------

I, the Renter, agrees that the Lessor may collect, use & disclose my personal data, as provided in this Schedule &/or pursuant to the Agreement from time to time, for the following purposes in accordance with the Personal Data Protection Act 2012 & the Lessor's group Private Policy for: -

- (a) administration of the vehicle rental under the Agreement;
- (b) for internal administrative purposes;
- (c) to communicate with me; &
- (d) for the Lessor to comply with its obligations under law.

Further, I understand that my personal data may be used for marketing purposes by the Lessor, its affiliated companies or their partners; & I hereby consent to receive marketing & promotional materials by telephone, SMS or email.




Additional Notes:

Subject to the Renter's fulfilment of Rental Tenure, Renter shall enjoy the followings:

- (a)
- (b)
- (c)
- (d)
- (e)

Agreement

The Renter has read, understood & agrees with all terms & conditions of this Agreement.

The Renter	For & on behalf of the Lessor
The Renter's Signature (& Company Stamp if applicable)	Authorised Signatory & Company Stamp
	 

Name: Chung Yee Siang
Date: 20 September 2019

Name: Ray Lim
Date: 20 September 2019

LETTER OF AUTHORITY

To Whom It May Concern:

ACCIDENT INVOLVING SLK 2376 C & STW 9285X along Balestier Road
On 27.10.2019 @ 22:55


I, GRAB RENTALS PTE LTD Nric No. 201617200G
of 18, Sin Ming Lane #01-08 Midview City Singapore 573960
Owner of motor vehicle no. SLK 2376 C do hereby appoint M/S
ESTEEM PERFORMANCE PTE LTD as my authorized representation and
_____ as my solicitors to write, to negotiate and settle my claim against
the other party/parties involved in the above mentioned accident. M/S ESTEEM
PERFORMANCE PTE LTD shall have absolute discretion to settle the matter at the best
terms.

I also confirm and instruct that any agreed settlement sum in respect of my claim be paid to
M/S ESTEEM PERFORMANCE PTE LTD and such payment will constitute a full and final
discharge of my claims.

I further authorize M/S ESTEEM PERFORMANCE PTE LTD to execute the discharge
voucher on my behalf.

Signature of Owner





Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 29 Oct 2019 / 19:18:10

Receipt Date/Time : 29 Oct 2019 / 19:18:10

Tax Invoice/Receipt

Receipt No. : ITNET-00000-191029-003058

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJJ2246Z				
As at 03 Oct 2019/13:30:00				
Insurance Co: NTUC INCOME INS CO-OP LTD				
1	Insurance Enquiry - SJJ2246Z Enquiry Fee 20191029191735515883	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - SJW9285X				
As at 27 Oct 2019/22:55:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
2	Insurance Enquiry - SJW9285X Enquiry Fee 20191029191735564030	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - SDX8684A				
As at 27 Oct 2019/12:25:00				
Insurance Co: NTUC INCOME INS CO-OP LTD				
3	Insurance Enquiry - SDX8684A Enquiry Fee 20191029191735600335	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		21.00	1.47	22.47
Rounding Difference				0.02
Total Amount Payable				22.45
Paid By				
	xxxxxxxxxxxx5823	Credit Card: Visa/MasterCard		22.45
Total				22.45
Cash Change				0.00
Tendered Amount				22.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



jenny chong <jenny@esteemperf.com.sg>

FINALISED SLK2376C

Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
To: jenny chong <jenny@esteemperf.com.sg>

Mon, Apr 6, 2020 at 9:10 AM

Final repair cost \$1454.61, 2days confirmed. Kenneth

From: jenny chong [mailto:jenny@esteemperf.com.sg]
Sent: Friday, 3 April, 2020 11:09 AM
To: Kenneth Kong (LKKAUTO)
Cc: Carmen Lim; serence ctc; Claim admin
Subject: FINALISED SLK2376C

Dear Frederick

Pls refer as attached.

Kindly confirm the finalised amount asap.

Thank you

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation

Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)
385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com

3/4

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJQ504E
Repairer Reference: 030932
Date calculated: 01/04/2020 10:12 AM

Full Report
Registration: SLK2376C
Printed: 01/04/2020 10:12 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SJQ504E	Date of Incident:	27/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLK2376C

VIN number:

Odometer:

Model Specs

TWO COAT METALLIC

Not Authorised

Repairing Blowing

2 days

01/04/2020 @ 18:30

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R		12.0	60.00
B410)	R + R REAR BUMPER REINFORCEMENT		1.0	5.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			1.30	13.0
Total of Labour				65.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		12.0	
	BOOT/T-GATE MOULDING REPAIR PAINT PLASTIC		11.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	55.10
2979	BOOT/T-GATE MOULDING REPAIR PAINT PLASTIC	15.80

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			23.0	
	Preparation Comp. Work Plastic		2.10	21.0	105.00
Total		10 WU/h	4.40	44.0	220.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	55.10
Repair Painting Plastic	15.80
Material-constant Plastic	18.10
Total	89.00

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2635	L/R BUMPER CORNER	52566 47900		149.70 7
2621	LEFT RETAINER	90467 09237		Sum 112.70 X
2636	R/R BUMPER CORNER	52565 47900		Sum 149.70 X
2583	REAR BUMPER	52159 47913		Sum 450.80
2640	REAR BUMPER REINF	52023 47030		398.90 7
2587	REAR COVER BUMPER	52453 47010		Net 582.60
2622	RIGHT RETAINER	90467 09237		Sum 112.70 X

Code	Description	Part Number	Supplier	Price SGD
1002	RR BMP CLIP	RR BMP CLIP		<i>nn</i> 40.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,997.10
u: Used parts	Subtotal Discount(+30.00%)			-599.13
	Total			<u>1,397.97</u>

Extras

Code	Description	Price SGD
1000	REVERSE SENSOR REVERSE SENSOR	<i>sm</i> 200.00* X
1001	REVERSE SENSOR TO R&R	120.00* <i>sol</i>
1003	TO TUFF COAT TO TUFF COAT	<i>nn</i> 100.00* X
	Total Extras	<u>420.00</u>

Final Calculation

	SGD	SGD
Parts	1,997.10	
Total Discount(+30.00%)	-599.13	
Total Parts		1,397.97
Labour Time Base 10 WU/h		
Total 13.0 WU X 50.00 SGD/h	65.00	
Total of Labour		65.00
Total Of Extras		420.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 50.00 SGD/h	220.00	
Material Cost	89.00	
Total Paint Including Material		309.00
Repair Cost Excludes GST		2,191.97
GST (+7.0%)		153.44
Repair Cost Included GST		2,345.41

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SJQ504E
Repairer Reference: 030932
Date calculated: 03/04/2020 11:00 AM

Full Report
Registration: SLK2376C
Printed: 03/04/2020 11:01 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SJQ504E	Date of Incident:	27/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: PRIUS IV
Sub Model: BASE MODEL
Model Sheet Number: 70 P5 01
Registration: SLK2376C
VIN number:
Odometer:

Model Specs

TWO COAT METALLIC


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R		12.0	60.00
B410)	R + R REAR BUMPER REINFORCEMENT		1.0	5.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		1.30	13.0	65.00
Total of Labour				65.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		12.0	
	BOOT/T-GATE MOULDING REPAIR PAINT PLASTIC		11.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	55.10
2979	BOOT/T-GATE MOULDING REPAIR PAINT PLASTIC	15.80

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			23.0	
	Preparation Comp. Work Plastic		2.10	21.0	105.00
Total		10 WU/h	4.40	44.0	220.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	55.10
Repair Painting Plastic	15.80
Material-constant Plastic	18.10
Total	89.00

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	52159 47913		450.80
2640	REAR BUMPER REINF	52023 47030		398.90
2587	REAR COVER BUMPER	52453 47010		582.60
1002	RR BMP CLIP	RR BMP CLIP		40.00
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				1,472.30

Subtotal Discount(+30.00%)	-441.69
Total	1,030.61

Extras

Code	Description	Price SGD
1001	REVERSE SENSOR TO R& R	50.00*
	Total Extras	50.00

Final Calculation

	SGD	SGD
Parts	1,472.30	
Total Discount(+30.00%)	-441.69	
Total Parts		1,030.61
Labour Time Base 10 WU/h		
Total 13.0 WU X 50.00 SGD/h	65.00	
Total of Labour		65.00
Total Of Extras		50.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 50.00 SGD/h	220.00	
Material Cost	89.00	
Total Paint Including Material		309.00
Repair Cost Excludes GST		1,454.61
GST (+7.0%)		101.82
Repair Cost Included GST		1,556.43

2 days ✓

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.