

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

14-05-20

Date of Accident : 28-03-2020

OUR REF : SKD 3504S/T/20

LIM KANG YAO, DEREK

Blk 179 Yung Sheng Road

#16-137

Singapore 610179

Alu. Lkh Asher
LKR - Mercedes.
limited
Repair
Date In/out: 28/03/20 to 14/04/20

Not Authorized
Lkh
2/5000
31/3/20
4 days.

VEHICLE NO : SKD 3504S

VEHICLE MODEL : MERCEDES BENZ E250

CHASSIS NO : WDD2073472F041215

LIST ITEM

Front Bumper Fascia	1516.22	DOJ	1,830.00	✓
Front Bumper Side Retainer		cne	68.00	✓
Front Bumper Clips	10pcs @ 4.50	nu	45.00	✓
Front Bumper Lower Garnish		su	156.00	X
Front Bumper Parking Sensor - RH	248	shaph	281.00	✓
Head Lamp - RH	3012.25	eng	3,178.00	✓
Head Lamp Nozzle - RH		cne	185.00	✓
Front Fender - RH & LH	2pcs @ 995.00	O/S surf/en	1,990.00	1/PC
Front Fender Chorme Moulding - RH & LH	2pcs @ 45.00	nu	90.00	✓
Front Fender Emblum 'Blue Efficiency'		nu	62.00	✓
Front Grille		su	1,300.00	X
			9,185.00	
Less Discount 10%:			918.50	
			8,266.50	

LABOUR CHARGE

To Check Wiring System.

80.00 20

To Respray Affected Areas.

800.00 600

To Renew Damaged Parts, Straighten & Repair & And Aligned All Parts.

750.00 300

To Reset Electrical Module System.

280.00 50

	10,296.50
GST 7%:	720.76
TOTAL AMOUNT:	11,017.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

656662